

Particulars	Details of actual measurement				Contents of area
	No	L	B	D	
Sth year Maintenance Bil					
N/W - Const. of Road From					
Gndauliya Ramchandra					
Singh Ke ghar Se Dakshin					
Se Memrey Pur Hote Hue					
Mohmadpur primary school					
To K.					
Agency :- Kumar Nilesh					
Ag No - 122 S.B. / 2019-20					
Date of work order - 5.11.2019					
Actual date of completion - 25.1.2021					

①	Restoration of rain				
	Cuts and berms.				
	$7 \times 9.35 \times .90 \times .30 =$				$17.67 m^3$
	$8 \times 9.30 \times .85 \times .30 =$				$18.97 "$
	$8 \times 6.95 \times .90 \times .30 =$				$15.01 "$
	$7 \times 7.25 \times .95 \times .30 =$				14.46
					C.C.P. = $66.11 m^3$
					Lt. $62.51 m^3$
2.	making up berms				
	and shoulder do 619				
	$4 \times 10.60 \times .90 =$				$38.16 m^3$
	$7 \times 6.85 \times .80 =$				$38.36 "$
	$8 \times 6.35 \times .85 =$				$43.18 "$
	$8 \times 11.20 \times .80 =$				$71.68 "$
	$7 \times 8.75 \times .90 =$				$54.97 "$
					C.C.P. = $246.35 m^3$
					Lt. $246.05 m^3$

Continuation

