

2nd year maintenance Bill

16

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Ch.H :-		NABARD			
Name of work:-		2nd year			
Maintenance of Road		Kodur			
Location		Muzaffar Nagar			
Pincode		501001			
Se. U. No.		101/10/101			
Dular No.					
Name of contractor:-		P. S. A.			
Address:-		Banbasa, PS -			
Block, Dist:-		Mysore			
Ass. No.:-		2018/19			
Date of commencement:-		24/01/2019			
Date of completion:-		21/10/2019			
Actual date of completion:-		4/5/2019			
Actual date of completion 2nd year					
2nd year maintenance:-		28/01/2024			
Measurement					
① Restoration of drain cuts etc.					
36x	1.30m	1.10m	0.30m	= 15.44m ³	
32x	1.20m	1.10m	0.30m	= 12.67m ³	
38x	1.40m	1.10m	0.30m	= 17.56m ³	
				45.56m ³	
② Maintenance of Earthen Bunds - 1					
4x	30m	1.10m	=	132.00m ²	
1x	22m	1.10m	=	22.00m ²	

Continuation

156.24m³

