

5th year maintenance bill

56

Sch. XLV—Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
N/W — PMGSY Road Se Vashimpur					
Kurda honyam talu					
Agency — Rajesh Kumar					
Agreement NO — 21530/2019-20					
ADOC — 10/2/20					
① Restoration of rain cut					
					9
	4	5.10	1.10	0.300	= 6.73 M
	7	5.05	1.10	0.300	= 11.66 "
	13	6.29	1.12	0.300	= 27.47 "
	13	6.37	1.05	0.300	= 26.08 "
	11	5.17	1.05	0.300	= 17.91 "
	15	10.84	1.10	0.300	= 53.70
					143.52 M ³
② Making up shoulder					
	14	6.10	1.10		= 93.94 M ²
	13	6.12	1.10		= 87.52 "
	17	5.38	1.20		= 109.75 "
	7	5.45	1.20		= 45.78 "
	9	5.09	1.10		= 50.39 "
	18	7.92	1.10		= 156.94 "
					544.32 M ²
③ Repair of pot hole filled					
with 75 mm. with B.M.					
	7	7	3.05	1.25	0.075 = 14.01 M ³
	9	7.10	1.25	0.075	= 5.99 "
	13	6.05	1.25	0.075	= 7.38 "
	13	6.70	1.22	0.075	= 7.96 "
	15	6.86	1.22	0.075	= 9.41 "
					44.75 M ³

Continuation

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
			8R	44.75 M	
		17x6.30x1.25x0.075=	10.040 "		
		17x6.77x1.25x0.075=	10.79 "		
		15x6.82x1.22x0.075=	9.36 "		
		15x7.05x1.25x0.075=	9.91 "		
		8x7.12x1.25x0.075=	5.34 "		
		8x7.33x1.20x0.075=	5.28 "		
		11x7.56x1.20x0.075=	7.84 "		
		13x8.40x1.20x0.075=	9.83 "		
		13x8.15x1.22x0.075=	9.69 "		
		7x5.09x1.20x0.075=	3.21		
					125.98 M ³
④ Patch repair of pot hole with 20mm thick					
		25x4.03x1.25=	125.98 M ²		
⑤ Patch repair over bituminous surface. Qty same as per ④ times NO ④					125.98 M ²
⑥ Maintenance of column pipe - 6 NO					
⑦ Maintenance of road signs - 24 km					
⑧ Maintenance of 200M ² km stone. 0.880 km					
9 ⑨ Cutting of branches - 3 NO					
⑩ Cutting of shrubs - 11 NO					
⑪ Trimming of grass - 27 M ²					
⑫ Road marking -					
		2x52x30x0.100=	312.0 M ²		
		2x1x15x0.100=	3.00		
					Continuation 315.0 M ²

36 512.04

Continuation

Continuation

Abstract of Cost

59

Sch. XLV—Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
① Restoration of raincuts					
avtpr-(56) 143.52M ³					
CR 365.25/M ³					R 52421=00
② Making up shoulder.					
avtpr-(56) 54.22M ²					
CR 54.16/M ²					R 29475=00
③ Repair of potholes.					
avtpr-(57) 126.98M ³					
CR 372.28/M ³					R 46899=00
④ Patch repair over pothole					
avtpr-(57) 125.98M ²					
CR 306.77/M ²					R 38646=00
⑤ Patch repair over bitumin surface. avtpr-(57)					
125.98M ²					
CR 328.55/M ²					R 41138=00
⑥ Maintenance of column pipe. avtpr-(57) 6 NO.					
CR 1131.64 each					R 6790=00
⑦ Maintenance of 200mm L					
km. avtpr-(57) 0.38km					
654.33					
CR 1087.62/km					R 297=00
⑧ Maintenance of road segins. avtpr-(57)					
0.240km					
CR 1087.62/km					R 257=00
⑨ Cutting of drains.					
avtpr-(57) 3 NO					
CR 107.48 each					R 322=00
⑩ Cutting of structures.					
avtpr-(57) 11 continuation					
CR 6.6 each.					R 73=00

Particulars	Details of actual measurement				Contents of area
	No.	L	B.	D.	
(25) Workup of grass.					
16770P-57 27.0 M ²					
CR 2.20/M²					R 59=00
(10) Road marking.					
16770P-57 315 M ²					
CR 942.89/M²					R 297010=00
(11) White washing.					
16770P-58 126 M ²					
CR 16.48/M²					R 2070=00
					R 515413=00
Less 0.11% bulrow (-)					R 567=00
					R 514846=00
28/12/24	28/12/24	28/12/24	28/12/24	28/12/24	
SC	AE	AE	AE	AE	

Continuation