

5th year Maintenance

Sch. XLV—Form No. 134

22

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Name of work - Maintenance					
of road of 30m.					
To, To Panchin Kabud					
West - East - 10/10					
Agency - Paja Kimari					
Agg No - 24 SCD 1203-12					
Date of Site - 21/09/17					
Date of Completion - 20/03/18					

① Restoration of	
Rain Cuts -	
$21 \times 2.10 \times 0.30 \times 0.30 = 10.58$	
$60 \times 2.40 \times 0.70 \times 0.30 = 30.24$	
$24 \times 2.00 \times 1.10 \times 0.20 = 10.56$	
Total = 51.38 m ³	

② Maintenance of	
earthen Shoulder	

$8 \times 4.00 \times 0.80 = 25.60$	
$9 \times 6.00 \times 0.90 = 48.60$	
$7 \times 5.00 \times 0.80 = 28.00$	
$17 \times 8.00 \times 0.74 = 100.64$	
$14 \times 4.00 \times 0.90 = 50.40$	
$24 \times 9.00 \times 0.50 = 30.00$	
Total = 283.24 m ²	

② Maintenance of	
------------------	--

Continuation

