

MMSY Five year maintenance
Schedule XLV-Form No. 134

Ag. NO-49503D 2019-2020

To 3 To Khariyat

Sheegraft

DIVISION

Dohki

SUB-DIVISION

Agency :- Sunderdas Kumar

MEASUREMENT BOOK

1363

4th Year Maintenance bill

1/

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Name of work- To 3 To 1 Kheriyat					
Agency - Surendar Kumar					
Aggroment No - 49 BDO/19-20					
item (1) perforation of Rain cuts					
	10	5.10	1.10	0.30	$= 16.83 M^3$
	12	4.50	1.15	0.250	$= 15.52 M^3$
	10	4.90	1.10	0.30	$= 16.17 M^3$
					<u>48.52 M^3</u>
item (2) Molding of berms/					
Shoulder					
	10	5.60	1.10		$= 61.60 M^2$
	12	4.90	1.15		$= 67.62 M^2$
	11	5.10	1.15		$= 64.51 M^2$
	10	3.70	1.10		$= 40.70 M^2$
	11	4.50	1.15		$= 56.92 M^2$
					<u>291.35 M^2</u>
item (3) repair of pot holes					
filled with 75mm W.B.M					
	2	0.350	0.250		$= 0.17 M^2$
item (4) Patching of pot holes					
Patched with 20mm					
Proximal Corbel					
	10	1.50	1.10		$= 16.50 M^2$
	12	1.80	1.20		$= 25.92 M^2$
	11	1.60	0.950		$= 16.72 M^2$
					<u>59.14 M^2</u>

Continuation



Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
item ⑤	patch repair over bituminous surface				
	11	1.50	1.10	=	22.99 m ²
	9	1.50	1.20	=	16.20 m ²
	10	2.10	0.95	=	19.95 m ²
					59.14 m ²
item ⑥	Filling of cracks and joints				
	20	30	=	600 m	
	1	25	=	25 m	
	1	24	=	24 m	
					649 m
item ⑦	Maintenance of CH-D drains				
	C-D works — 180				
item ⑧	Maintenance of C-D slab culvert — 24				
item ⑨	Maintenance of Road sign — 0.66 km				
item ⑩	Maintenance of 200 and 100 gms — 0.66 km				
item ⑪	Cutting of branches of trees — 44				
item ⑫	Cutting of shrubs from road way				
	1	658	=	658 m	

Continuation

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Ida (13) Trimming of grass and weeds					
		2 x 22.80	1.12	=	14.78 m ²
Ida (14) white washing of parapet					
		2 x 4 x 3.40	1.2	=	32.64
		2 x 2 x 3.40		=	13.60
					<u>46.24</u>
Atunay 16/12/24 2 Chaitanya 16					

<u>Abstract of GST</u>					
(1/15/18) Restoration of Ramees/ Berms with soil					
		V.T.P.R.P.No - (151)			
		Ida No (1) - 48.52 m ²			
		8 386.14 m ²			18736-m
(2/15/20) Maching up of Bony shoulder					
		V.T.P.R.P.No - (17)			
		Ida No (2) - 291.35 m ²			
		8 57.36 m ²			16712-m
(3/15/5) Repair of postholes filled with JSDM					

Continuation

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
	V.T.M.B.P.H. (17)				
	item (17) — 0.12 m ²				
	Q 930.457/m ² — 1582.00				
(9/153ii)	Patch repair over				
	Pot holes				
	V.T.M.B.P.H. (17)				
	item (17) — 59.14 m ²				
	Q 240.18/m ² — 14204.00				
(5/153ii)	Patch repair over				
	Bituminous surface				
	V.T.M.B.P.H. (18)				
	item (18) — 59.14 m ²				
	Q 257.30/m ² — 15247.00				
(6/)	Filling of cracks				
	and joints				
	V.T.M.B.P.H. (18)				
	item (18) — 64.92 m ²				
	Q 3 = 96/m — 2570.00				
(7/)	Maintenance of H.P.				
	culvert				
	V.T.M.B.P.H. (18)				
	item (18) — 1.10 m ²				
	Q 1130.67/m ² — 1131.00				
(8/)	Maintenance of slab				
	culvert				

Continuation

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
	V.T.M.B.P.H.	(18)			
	Item (8)			240	
	Qs	2329.24/m			4658.2
(9)	Maintenance of				
	road sign				
	V.T.M.B.P.H.	(18)			
	Item (9)			0.661m	
	Qs	6077.81/m			711.20
(10)	Maintenance of				
	and telephone				
	V.T.M.B.P.H.	(18)			
	Item (10)			0.661m	
	Qs	628.22/m			415.2
(11)	Cutting of branches				
	of tree shrubs				
	V.T.M.B.P.H.	(18)			
	Item (11)			440	
	Qs	109.74/m			439.2
(12)	Cutting of shrubs				
	from road side				
	V.T.M.B.P.H.	(18)			
	Item (12)			658 m	
	Qs	6.73/m			4428.2
(13)	While working of				
	work of paper				
	V.T.M.B.P.H.	(15)			
	Item (13)			46.24 m ²	

Continuation

Scanned with OKEN Scanner