

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
5th year Maintenance					
Name of work - Maintenance					
of road from X-Road					
Mahab to Tanza Taradix					
Agency - Rampokar Sahni					
Agreement No. - 58 SBZ/2018-19					
Date of work - 1.12.2019					
1. Restoration of Ruin					
cutts with cul empty					
10 X 15m X 75 X 30				233.25 m ³	
5 X 15m X 60 X 30				=13.50	
				47.25 m ³	
2. making up Boring					
Shoulder - -					
15 X 15m X 90				202.50 m ²	
7 X 15m X 75				78.75	
				281.25	
				Net - 281.08 m ²	
3. Repair of pot hole					
fill-up with sand - -					
24 m ² X .075				=1.8	
6 m ² X .075				=0.45	
				2.25 m ³	
				Net 2.20 m ³	
4. patch Repair pot					
hole. 4 X 3 m X 2 m					
				24 m ³	

Continuation