

Tankuppo
MES H. KUMAR

Schedule XLV Form No. 134.

M.M.G. S. Y. Aug 2015 (SC)

24 1048

F.F. R.O.D(u)

DIVISION

kradga

A.F. R.O.D(u)

SUB-DIVISION

Tankuppo

Measurement Book

Executive Engineer
Executive Engineer
Road Works Div.

RWD

2

1

Name of Work-

Situation of Work-

Agency by which work is executed-

Date of Measurement-

No. and date of agreement

(These four lines should be repeated at the commencement of the measurement relating to each work)

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Name of Work - Construct of Road					
From Saluradih TO L048					
with Five year Mainten					
under Head MM 454 (SC)					
Name of Agency - Umesh Kumar,					
Vill + P.O. - Utali Bana					
(A/Surain), Tan Kuppa,					
Distt - Gaya.					
Agreement No. - 81/MM 454/4/SBD/					
2020-21					
Date of Commencement - 30.12.20					
Date of Completion - 29.12.21					
Date of measurement - 4.8.21					
(1) E/W in excavation					
of Structure - - - etc					
(1000 mm ϕ H.P.C - 04 Nos)					105.84
H.W. - $4 \times 2 \times 6.30 \text{ m} \times 1.40 \text{ m} \times 1.50 \text{ m}$					26.46 m ³
Pipe post - $4 \times 1 \times 5.90 \text{ m} \times 1.50 \text{ m} \times 0.30 \text{ m}$					10.62 m ³
(1000 mm ϕ H.P.C - 04 Nos)					116.46 m ³
(2) P.W. P.C.C. M15 in open					
found - - etc (1000 mm ϕ H.P.C - 04 Nos)					
H.W. - $4 \times 2 \times 6.30 \text{ m} \times 1.40 \text{ m} \times 0.15 \text{ m}$					10.58 m ³


Continuation

1st year maintenance Bill

57

Sch, XLV-Form No. 134

M.D. MOUKA D.A. G.S. S. EXHIBIT F. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Name of work:- Construction of Road from Salukadeh to W48 with 5 th year maintenance					
Under Head MMBGsy (SC)					
Agency:- Umesh Kumar					
NITFP - Udaipur, Assam.					
Tankura.					
Dist- Gaya					
Agreement No. 81/MMGsy/SC/SBD/2020-2021					
Date of Commencement - 31.12.20					
Date of Completion - 21.12.21					
Date of Actual Completion - 15.9.23					
① Restoration of Road cuts/Berms					
					
$5 \times 30.0 \times 0.60 \times 0.30 = 27.0 \text{ m}^3$					
$2 \times 25.0 \times 0.60 \times 0.30 = 9.0 \text{ m}^3$					
$1 \times 15.0 \times 0.75 \times 0.30 = 3.375 \text{ m}^3$					
$2 \times 25.0 \times 0.60 \times 0.30 = 9.0 \text{ m}^3$					
$3 \times 30.0 \times 0.60 \times 0.30 = 16.2 \text{ m}^3$					
Total = 64.575 m ³					

Continuation

ABSTRACT OF COST 2nd year maint. 8011 82

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
(1) Restoration of Rear cbs/Bermado					
64.575m ³ fly-truss Page (58)					
@ £404.06/m ³					£26092=0
(2) Making up Bems/ Shoulder do do					
369.00m fly-truss Page (58)					
@ £60.28/m					£22243=0
(3) Patch repair over Pop holes					
200m Francis Carpet do do					
30.72m ² fly-truss Page (58)					
@ £231.63/m ²					£7097=00
(4) Patch repair over Bituminous surface					
200m Moss do					
30.72m fly-truss Page (58)					
@ £247.15/m					£7592=0
(5) Filling of cracks					

Continuation

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
and joint excluding					
do do					
1319.0 m ² by Mrs Page (58)					
@ ₹ 3.71/m					₹ 4833.00
(6) Repair of isolated					
area of damaged					
Concrete pavement					
do do					
8.22 m ² by Mrs Page (59)					
@ ₹ 231.03/m ²					₹ 1899.00
(7) Repair of old					
joint sealant					
do do					
336.0 m by Mrs Page (59)					
@ ₹ 24.13/m					₹ 8108.00
(8) Maintenance of					
CD work (for job)					
4.0 m ² by Mrs Page (59)					
@ ₹ 1166.58/m ²					₹ 4666.00
(9) Maintenance of					
CD work					
(S/s culvert)					
do do					

Continuation

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
2970.00m dy ring page					
no. 69/14					
@ 2.33/m					6920.00
(15)					
1st white washing					
of Porafet wall					
of CD wall &					
Slab culvert					
— do — do —					
99.20m dy ring page 61					
@ 2 16.80/m					1666.00
total = 103720.00					
Add G.S. @ 12%					12446.20
Add L.C.S. @ 1%					1037.20
					211720.30
Signature					
JE					