

Particulars	Details of actual measurement				Contents of area
	No.	L	B	D	
1st year maintenance bill					
Name of road: - Tilauthi to Bhado					
Chakr 9 (Kro path) (Saw to 19 nose)					
to Saw to 19 (Maha to 19)					
Agency: - Rajesh kumar Yadav					
Agreement No: - RWD/Dehri/18-MNHG					
SBD/2020-21					
Actual date of completion: - 09.06.					

MEASUREMENT OF ROAD WORKS
 MEASUREMENT OF ROAD WORKS
 MEASUREMENT OF ROAD WORKS

① Restoration of road cut etc

2

$$111 \times 1.65 \times 0.30 \times 0.30 = 16.48 \text{ m}^3$$

$$20 \times 1.70 \times 0.40 \times 0.40 = 5.44 \text{ m}^3$$

$$21.92 \text{ m}^3$$

② Maintenance of earthen

shoulders etc

$$6 \times 30.00 \times 1.00 = 180.00 \text{ m}^2$$

③ Maintenance of CD worker

2.00 Nos

④ Patch repairs on already

filled potholes with 75mm Bore

$$38 \times 0.60 \times 0.45 = 10.26 \text{ m}^2$$

Recd

04.01.25

TE

Continuation

Particulars	Details of actual measurement				Contents of area
	No.	L	B	D	
Abstract of Loss					
① Restoration of drainage etc					
Qty: - 21.92 M ³ from TMRP-26					
② 394.20					RS 8641.00
② Maintenance of road etc					
Qty: - 180.00 M ² from TMRP-26					
③ 58.97					RS 10615.00
③ Patch repairs already filled by 75mm ASP etc					
Qty - 10.26 M ² from TMRP-26					
④ 252.50					RS 2591.00
④ Maintenance of CD WORK etc					
Qty - 2.00 M ² from TMRP-26					
⑤ 1130.67					RS 2261.00
					24108.00
					less 24.66% (-) 5931.00
					18177.00
					Qty 18177/-
					@ 100/-
					04.01.25
					JE
material statement					
① Earth - 48.92 M ³					
② RS-1 : - 0.002 MT					
③ SSB : - 0.019 MT					
④ Stone Agg : - 0.28 M ³					
					@ 100/-
					04.01.25
					JE

Continuation

JE