

Gajekhuch Ramnagar to Nanded

MMGSY (Gen)

Schedule XLV-Form No. 134

Karhaiya Kumar

E. E. R. W. D. (w)

DIVISION
GHYA

A. E. R. W. D. (w)

SUB-DIVISION
BODHGHYA

Measurement Book

2793

(2)	Restoration of main cuts				
-----	--------------------------	--	--	--	--

Continuation

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
		Abstract of cost			
(1)		Restoration of drain			
		cub.			
P/28		23.8443			
		C 380=58			b= 9073=00
(2)		Making up of Roadways			
P/28		132.4742			b= 7732=00
		C 58=37			
(3)		Repair of pot hole			
P/28		0.0343			
		C 10494=12			b= 315=00
(4)		Patch repair on road			
		pot holes			
P/28		11.0442			
		293=69			3242=00
		C 294=35			b= 3288=00
(5)		Patch repair on road			
		Bituminous			
P/28		11.0442			
		C 297=85			b= 3288=00
(6)		Filling of cracks and			
		Joint			
P/28		47.004			
		C 4=69			b= 8209=00
(7)		Repair of isolate			
P/29		5.8142			
		C 293=69			b= 1706=00
(8)					

Continuation

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
(14)	Trimming of grass and weeds				
P/29		1060.00 M ²			
	Q	2 = 18		6 = 2311 = 00	
(15)	Wide walking of parapet				
P/29		42.00 M ²			
	Q	16 = 21		6 = 681 = 00	
				6 = 42561 = 00	
Less 10/1 Below				6 = 4256 = 00	
				6 = 38305 = 00	

(16) 1/10/22
TC

Material statement

(1) E/W - 23.84 M³
(22) S/C/6/8 - 0.29 M³
(222) Bitumening - 0.02 MT

Continuation

16/10/22
TC

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
<u>2nd Year Maintenance</u>					
<u>Name of Work - Const. of rural road</u>					
<u>from Gafakhand Ramnagar</u>					
<u>to Nandur under HHsy.</u>					
<u>Agency - Kamlaiya Kumbal.</u>					
<u>Agg No - 41/SB01/HHsy/Genl 2019-20</u>					
<u>Daw - 3.08.19</u>					
<u>To C - 3.05.20</u>					
<u>Date of final measurement - 16.10.20</u>					
(2)	Restoration of drain cut.				
				28.61 M ³	
(2)	Making up of Boaroms stripping excess soil.				
				158.96 M ²	
(3)	Repair of Pot holes				
				0.07 M ²	
(4)	Patch repair over Pot holes.				
				22.08 M ²	
(5)	Patch repair over Bituminous.				
				22.08 M ²	

Continuation

Sch. XLV-Form No. 134

Sch. XLV - Form No. 134					Contents of area	
Particulars	Details of actual measurement					
	No.	L.	B.	D.		
		<u>Abstract of Cost</u>				
(1)	Restoration of rain cuts.					
P/34		38.614 ³				
		C 280 = 58		R = 10888 = 00		
(2)	Making up of Beams					
P/34		158.964 ³				
		C 58 = 37		R = 9278 = 00		
(3)	Repair of pot holes					
P/34		0.074 ²				
		C 10494 = 12		R = 735 = 00		
(4)	Patch repair over pot holes.					
P/34		22.484 ²				
		C 293 = 69		R = 6485 = 00		
(5)	Patch repair over bituminous.					
P/34		22.034 ²				
		C 297 = 85		R = 6577 = 00		
(6)	Filling of cracks and Joints.					
P/39		471.004				
		C 4 = 69		R = 2209 = 00		
(7)	Repair of isolated areas.					
P/39		11.634 ²				
		C 293 = 69		R = 3416 = 00		

Continuation

Speed
10/10/22
JE

(2) E/W - 28.61 m³

(22) Stone clips - 0.59 m³

(222) Gunter clip - 0.04 m

16/10/22
JE