

Manikonda Taluk, Maheswari  
Pancharayet Bhawani Dosa

Schedule XLV-Form No.-134 Maheswari (SC)

E. E. R. L. D. (IV) DIVISION

A. E. R. L. D. (IV) SUB-DIVISION

BODHAPURAM

**MEASUREMENT BOOK**

payee fd - P T 752084

MSR - 10AHFH5372.D

2956

1st Year Maintenance  
BMD NAGAR DAWAT CEM  
EXECUTING ENGINEER,

24

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Name of WMR:	1ST Year Maintenance				
of road from	Dawat				
Ilera Cherkir road Rd					
Pringayat Bawarw Ilera					
Kotrapur 12/19/20					
Agency:	Hari Krishan Const				
Act No:	82/M/Nagay/SC/2021				
Date:	30-12-20				
Actual Date of Completion:	23.3.21				
Date of Measurement:	25.3.22				
W.M.R. No:	12/19/20				

- ① Repair of concrete pavement  
with premix carpet due to  
 $Q, w \times 2.40 = 4,80 \text{ m}^2$
- ② Repair of old joint  
Sealant due to all  
190 Ml
- ③ Maint of road sign due to  
0.21 Km
- ④ Maint of 200m & Km, stone  
0.21 Km
- ⑤ cutting of branch of tree  
0.1 Nos

Signature

TD 25.3.22 Continuation

25

Sch. XLV-Form No. 134

*Conrad*  
28.3.22  
*Contin*

## **Continuation**

## 2nd Year Maintenance

27

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Name of work:	2nd Year Maint				
of road from A to B					
A : ILas Charki road To bridge					
B : Bhawar Iler under Mysore					

Agency: Hari Krishana Const

Ref no.: 82/Mys/SC/20-21

Date: 30-12-20

Actual Date of Completion: 23.3.21

Date of Measurement: 16-1-23

① Repair of Concretement  
with Pressix Carpet

$$3.25 \times 2.95 = 9.58 \text{ m}^2$$

② Repair of old sealant

190.00 m

③ Maint of road sign

0.21 Km

④ Maint of gason & Kastone

0.21 Km

⑤ cutting of Boscach of tree

02 nos

Report	✓	✓	✓	✓	✓
Date	16-1-23				
Signature					
Signature					
Signature					

Continuation

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
<u>ABSTRACT OF COST</u>					
① Repair of Conc Pavement with Poemix Carpet - vde PmB P27					
9.58 m <sup>2</sup> @ Rs 227.65					Rs 2181.00
② Repair of old joint Sealant duds - vde PmB P27					
190.00 m @ Rs 24.13					Rs 4585.00
③ Mount of road sign vde PmB P27					
0.21 Km @ Rs 1104.59					Rs 232.00
④ Mount of 2 arm & km vde PmB P27					
0.21 Km @ Rs 643.17					Rs 135.00
⑤ cutting of Branch of tree 02 nos @ Rs 113.64					
					Rs 227.00
					Rs 7366 = Rs
Less 0.09% Belm 7.00					
					Rs 7353 = Rs

Continuation

JF 16-1-23

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Name of work - 3rd year Main + of road from D no 100m to Charki road to Parachayet Bhawan Illeg under H.H.S.Y.					
Agency - Hazri kolsaon const.					
Ag H No - 821 HMGSY / SC 20-3					
Date - 30.12.20					
Actual date of completion - 23.03.21					
(1) Repair of isolated areas.	14.41 $m^2$				
(2) Removal of existing Sealant.	19.2.19 m				
(3) Cement Concrete paving.	41.00 $m^2$				
(1) Total	53.24				
(2)	20.53.24				
(3)	11.00				
Total	84.77				
Other	0.00				
Total	84.77				

## Continuation

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Abstract of cost					
(1) Repair of isolated areas.					
P   30		14.414 <sup>2</sup>			
	(C)	2.47 = 65	b = 3280 = 00		
(2) Removal of existing sealant.					
P   30		19.2.194			
	(C)	2.4 = 13	b = 4638 = 00		
(3) Cement concrete portion.					
P   30		41.004 <sup>2</sup>			
	(C)	870 = 17	b = 35677 = 00		
Less 0.09 / .00 -			b = 43595 = 00		
			b = 39 = 00		
			b = 43556 = 00		
Grand Total					
		200384			
		J.E			

### Continuation