

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Name of work :- Ekangar Rasalpur					
to Dharampur					
Agency :- Kunj vihari					
ASS No :- 63/SBD/18-19					
Actual date of completion :- 26/02/20					
① Restoration of Raincoat					
Berry with soil :-					
1x10x27x0.8x0.3 =					65.0m ³
② maintenance of Berry /					
Shoulders					
2x4x30.0m x 0.80m =					192.0m ²
2x23.50m x 0.90m =					42.3m ²
2x2x30.0m x 0.95m =					114.0m ²
2x10.0m x 0.75m =					15.0m ²
total =					363.30m ²
③ Repair of Pot holes Filled					
with 75mm BM :-					
1x22x3.75x0.075 =					6.187m ³
④ Patch Repair over Pot					
hole with 20mm :-					
1x22x3.75 =					82.5m ²
⑤ Patch Repair over bit					
surface with 20mm =					82.5m ²
⑥ maintenance of CD					
work (H.P)					5 Nos.
⑦ white washing of					
Parapet wall =					105m ²

Continuation

ABSTRACT

67

Sch. XLV—Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
① Restoration of Rainub wide item no. ① VIMP 60					
Qty = $8 \text{ m}^3 @ 380.52/\text{m}^3$					24734-
② maintenance of Berms / Sloops wide item no. ② VIMP 66					
Qty = $\frac{363.30\text{m}^2}{\text{Limit } 361.97} @ 57.31/\text{m}^2$					20745-
③ Repair of Pothole 75mm BM wide item no. ③ VIMP 66					
Qty = $6.2 \text{ m}^3 @ 9894.46/\text{m}^3$					61346-
④ Patch Repair over Potholes Wide Item No. ④ VIMP 66					
Qty = $82.5 \text{ m}^2 @ 270.52/\text{m}^2$					22318-
⑤ Patch Repair over Roadside wide item no. ⑤ VIMP 66					
Qty = $82.5 \text{ m}^2 @ 286.77/\text{m}^2$					23678-
⑥ maintenance of CD work Qty = 5 nos. @ 1117/each					5585-
⑦ White Washing of Parapet wide item no. ⑩ VIMP 66					
Qty = $105 \text{ m}^2 @ 16.27/\text{m}^2$					1708-
				Total =	16011/-
				(-) less 0.25% = (-) 400	
				total =	159711/-
<i>Samesh</i> <i>08/10/25</i> <i>A.E</i>					
<u>material statement</u>					
⑧ C/WORK - 65 m^3					
<i>Samesh</i> <i>08/10/25</i> <i>A.E</i>					

Continuation