

Kormathu to Basan Bisga (C.M.S.S.)
MMBSY (SC)

Schedule XLV-Form No. 134

Executive Engineer, R.W.D. DIVISION
Tekari

Assistant Engineer R.W.D. SUB-DIVISION
Belagani

MEASUREMENT BOOK

Akhilesh Singh

(740)

2nd year Maintenance Bill

28

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Name work - Const ⁿ of Road from Karmatho to Basam Bigha					
Name of - Akhilesh Singh Ist					
Saketpur Gilling Rampur Gaya					
Agri No - 295 BD / MMS / 2019-2020					
Date of Commencement - 16-8-2019					
Date of Completion - 15-5-2020					
Date of Measurement - 26-5-20					
(1) Restoration of Raincuts with					
Sail moorum - - Job					
$8 \times 2.00 \times 1.15 \times 0.30 = 5.52 \text{ m}^3$					
$11 \times 3.00 \times 1.00 \times 0.30 = 9.90 \text{ m}^3$					
$12 \times 3.25 \times 1.25 \times 0.30 = 14.62 \text{ m}^3$					
$9 \times 2.25 \times 1.15 \times 0.30 = 6.98 \text{ m}^3$					
Total					37.02 m ³
Limit					= 36.21 m ³
(2) Making up of shoulder stripping excess soil from - - Job					
$15 \times 3.00 \times 1.70 = 49.5 \text{ m}^2$					
$12 \times 3.30 \times 1.00 = 39.60 \text{ m}^2$					
$15 \times 2.00 \times 1.00 = 30.00 \text{ m}^2$					
$9 \times 3.00 \times 1.25 = 33.75 \text{ m}^2$					
$12 \times 3.20 \times 1.30 = 49.92 \text{ m}^2$					
Total					202.77 m ²
Limit					= 201.15 m ²
(3) Patch repairs over Bituminous					

Continuation

Particulars	Details of actual measurement				Contents of area
	No.	L ^y .	B.	D.	
Surface with Comp					Job
8x	1.10x	0.90	=	7.92m ²	
10x	0.90x	0.80	=	7.20 "	
9x	1.0 x	0.60	=	5.40 "	
7x	1.25x	0.90	=	7.87 "	
			Total	28.39m	
			link	27.94m	
(4) Maintenance of CD work					
Home pipe Culvert →					2 Nos
(5) Maintenance of Road					
Signs —————					0.07 km
(6) Maintenance of					
200mmrd krm stones ————					0.09 km
(7) Cutting of branches of trees and shrubs ————					4 Nos
(8) Cutting of shrubs from roadway ————					596 NOS
(9) Trimming of grass and weeds ————					295 NOS m ²
(10) White washing of parapet walls of CD work Job ————					42 m ²
20/9/23 S.B					
10/10/23 A.R					

Continuation

Sch. XLV-Form No. 134

Sch. XLV-Form No. 134					Contents of area
Particulars	Details of actual measurement				
	No.	L.	B.	D.	
Abstract of Cost					
(1) Restoration of Barricade with Soil 36.21 m ³ vide					
per cu (28) @ 380.58 m ³					= 13781.00
(2) Making up of shoulder stripping excess soil					
Qty 201.5 m ² v.p. (28)					
@ 58.37 m ²					= 11741.00
(3) Patch repair over Bituminous Surface					
Qty 27.94 m ² v.p. (29)					
@ 264.65 m ²					= 7394.00
(4) Maintenance of (10) arch					
than Home pipe Culvert					
Qty 2 Nos v.p. (29)					
@ 1117.00 Each					= 2234.00
(5) Maintenance of road sign					
Qty 0.07 km v.p. (29)					
@ 1074.51					= 75.00
(6) Maintenance of 200 m and km stones					
Qty 0.09 km v.p. (29)					
@ 657.71					= 59.00
(7) Cutting of branches of tree					
Qty 4 Nos v.p. (29)					
@ 106.52 each					= 426.00
Continuation					24710

Continuation

34710

Continuation