

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
1. N/A - Chand prasad to Baki to Laksh					
2. N/A - Sanjay k. Singh					
3. Ag. No. - Mngy 4/80 - 88/2021-22					
		wired down			
CD Restoration of saint					
	1 x	8.85	0.80 + 1.65	1.60	17.35m
	2 x	2.70	0.95	0.90	6.93m
					24.28m
CD maintaining earthen Shool					
	5 x	30	0.80	2	120m ²
	1 x	18	0.85		15.30m ²
					135.3m ²
					Ltd 135.0m ²
3. Repairs to pot holes					
	1 x	4.9	2.3		11.27m ²
					Ltd 11.25m ²
4/10. number of 20mbs & km					
		1025.5m	23	1.03 Km.	

Particulars	Details of actual measurement			Contents of area
	No.	L.	B.	
① Restraining wall				
	T.M. 10.31	24.28m		
	Q.B. 10.31	24.28m	-B	28.112m
② Maintenance of earthen shoulder				
	T.M. 10.31	135.0m		
	Q.B. 10.31	28.1m	-B	8138.20
③ Repair to pot hole				
	T.M. 10.31	11.25m		
	Q.B. 10.31	16.1m	-B	2904.2
4/10 Maintenance 200m ² < 149				
	T.M. 10.31	1.03m		
	Q.B. 10.31	22.1m	-B	793.20
				521,646.20
Add				
10% Lab fees			+B	216.20
10% GST			+B	2598.20
Seigniorage			-B	133.88
④ Restraining wall				
	Q.B. 10.31	24.28m	-B	63.39
⑤ Maintenance of earthen shoulder				
	Q.B. 10.31	24.28m	-B	70.49
				Net E. 2,593.88
11/09/2024 AE, Khanh				