

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
	2nd Year Maint				
Name of Work: — Maint of Rd.					
Galden Patti Se to Geniyq					
Gao Ke Age Kumbhraw Siwan TqK.					
Agency: — Jady bansh Kr. Singh.					
Agreement No — MMGRY WB / NDB-50/					
2020-21					
Actual dt of Comp — 15/6/22					
<u>Measurement</u>					

1. Restoration of Rain Cuts with					
Soil -- T/b.					
20x	4.0	0.90	0.60	= 43.20m ³	
25x	3.0	0.90	0.60	= 40.25m ³	
20x	2.0	0.90	0.60	= 21.60m ³	
28x	1.8	0.90	0.60	= 27.22m ³	
16x	2.5	0.90	0.60	= 21.60m ³	
18x	3.5	0.90	0.60	= 34.02m ³	
64x	1.50	0.9	0.40	= 34.56m ³	
30x	3.80	0.90	0.60	= 61.56m ³	
Total				= 284.01m ³	
2. Planting & Maint of Tree					
Qty = 50 No					

Continuation