

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
	<u>2nd year Maint</u>				
Name of work - Maint. of Rd.					
Mahpur Vishwanath Rajak house					
Se Bashauli Siman AHP Ray					
House.					
Agency - Anil Kumar					
Agg. No - MMGSY/ 3B2 - 38/					
2018-19					
Actual dt of Coml -					
10/3/22					

1. Restoration of Rain Cuts with					
Soil - T/A.					
$22 \times 2.0 \times 0.80 \times 0.60 = 21.12 m^3$					
$20 \times 2.2 \times 0.80 \times 0.60 = 21.12 m^3$					
$15 \times 1.50 \times 0.80 \times 0.30 = 5.40 m^3$					
$11 \times 1.10 \times 0.80 \times 0.30 = 2.90 m^3$					
Total = 50.54 m ³					
2. Maint of earthen Shoulder - T/A					
$10 \times 10 \times 0.80 = 80 m^3$					
$12 \times 8 \times 0.80 = 76.80 m^3$					
$10 \times 15 \times 0.80 = 120 m^3$					
Total = 276.80 m ³					

Continuation

Continuation