

5th year Maintenance bill

55

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
N/W - Maint. of Road Hajam Gela to Jagat Narayan ke ghar tak					
N/A - Bacchalal Ray					
Ag. No. - MMSY/SBD/-2/00-21					
Actual Date of Completion					10/11/21
<u>Measurement</u>					
(1) Maint. of Raincut with soil					
	3x	2.5x	0.9x	0.6	= 4.05 m ²
	5x	2x	0.9x	0.6	= 5.4 m ²
	5x	2x	0.9x	0.3	= 2.7 m ²
	7x	1.5x	0.9x	0.3	= 2.84 m ²
	7x	1.8x	0.9x	0.6	= 6.80 m ²
					total = 21.79 m ²
(2) Limit					Limit = 21.60 m ²
(2) Maint. of Earthen Shoulder as T/S					
	6x	8x	0.9		= 43.2 m ²
	9x	5x	0.9		= 40.5 m ²
	7x	4x	0.9		= 25.2 m ²
	6x	2x	0.9		= 10.8 m ²
					total = 119.7 m ²
(3) Repair of pot holes with MSS T/S					
	5.70x	3.75			= 21.37 m ²

Continuation

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
[5] Patch Repair on already filled pot holes with 75mm W.B.M. Grade as per T/S 21.37 m ² vide T.M.B P-56 @ 266.03/m ² 5685					
[6] Maint of H.P Culvert as per T/S Qty. = 1 number vide T.M.B P-56 @ 1166.58/number 1166					
[7] Maint of 200m and km Stone as per T/S Quantity = 0.630 km vide T.M.B P-56 @ 748.22/km 471					
Total					119882
Add 0.59 12%					21579
Add 1.00 1%					1199
8F					198
Total					142858
Less 21.69% below (-)					30986
Total					111872

Continuation

6/10/24