

CHAMAR TOLi To DHODIYAHi TOL,

Schedule XLV-Form No. 134

MANUSY-SC
(MAINTENANCE)

BE NIPUR

DIVISION

BE NIPUR

SUB-DIVISION

MEASUREMENT BOOK

220-22014/392511

M.B.N. - 1390

220-22014/392511

116/2012/251
10 IV 11 Jan 2012

Sch. XIV Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
1) Restoration / Paints					
106.33m ² @ V 7ms R.N					14-15
@ 338.45/m ²					42331-
2) Make up / Beom / Shoulder					
Stop 08/12					
600.35m ² @ V 7ms R.N					15-16
@ 54.16/m ²					32515-
3) Repair / pot hole / valley					
with 75mm BM					
9.06m ² @ V 7ms R.N					16-17
@ 10254.77/m ²					92902-
4) patch repair over holes					
with 13.2mm ± 0.03mm					
M. 3.5.					
120.96m ² @ V 7ms R.N					17-18
@ 212.72/m ²					25731-
5) Maintenance / C.D					
H.P.C					
5N @ V 7ms R.N					18
@ 1131.64/ceft					5658-
6) Maintenance / Red Sign					
1.37km @ V 7ms R.N					18
@ 1055.94/km					1447-

Rs 200650=

Continuation

BF 200650-

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
7/10) Maintenance / 200m and 1 km. stone					
1.37 km CV / 100 P.M.					18
610.85 / km					837-
8/12) White Washing / parapet wall					
83.2 m ² CV / 100 P.M.					18
15.98 / m ²					1425-
					A 202912-
Less 10% below					202912-
					R 182621-

08-05-2024
J.F.L. (Bom)

08-05-2024
J.F.L.

Material

- ① Soil → 196.44 m³
 ② Stone chpt - 16.11 m³
 ③ R31 - 0.184 m³
 ④ S90 - 0.924 m³

08-05-2024
J.F.L. (Bom)

Continuation