

Name of work: messy SC const. of road works. Kumbhaja te
relavi toke.

Schedule XLV-Form No. 134

Picked
Sketch of HIL DIVISION

FINAL SUB-DIVISION

M Messy (SC)

Measurement Book

SHU

2505

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
4th Year Maint.					
Name of Road: - Repairs of Road from Kumharas to Nali Tola.					
Name of Agency - Smt. Dilip Kumar					
Agreement No. - SPD 10 of 2019-20					
Date of measurement: - 15/10/24.					
1. Restoration of rain cuts with soil compaction etc.					
					$2 \times 2.5m \times 1.0 \times 0.30 = 1.5m^3$
					$2 \times 1.8m \times 1.10 \times 0.30 = 11.88m^3$
					$2 \times 1.5m \times 0.9 \times 0.30 = 8.10m^3$
					$2 \times 2.0m \times 1.0 \times 0.30 = 12.00m^3$
					$2 \times 2.5m \times 0.9 \times 0.30 = 13.50m^3$
					$2 \times 2.0m \times 1.0 \times 0.30 = 12.00m^3$
					$2 \times 2 \times 2.5m \times 1.0 \times 0.30 = 30.00m^3$
					$2 \times 2 \times 2.0m \times 1.10 \times 0.30 = 26.40m^3$
					$2 \times 2 \times 1.5m \times 1.0 \times 0.30 = 18.00m^3$
					$2 \times 3.0m \times 1.0 \times 0.30 = 1.80m^3$
					164.88m ³
2. Making up of Berms/Shoulders of access					
					147.83m ³

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
				1811	53.600
	2	30m		0.90m	54.00m ²
	2	25m		0.80m	80m ²
	2	20m		0.60m	48m ²
	2	30m		0.70m	45.60
	2	22m		0.70m	30.80m ²
	2	20m		0.60m	24.0m ²
	2	23m		0.50m	23.0m ²
	2	20m		0.60m	24.0m ²
	2	18m		0.50m	18.0m ²
	2	22m		0.60m	26.40
	2	30m		0.90	54.0m ²
	2	25m		0.70	76.0
	2	30m		0.80m	48.0m ²
	2	4		0.50	4.0m ²
					609.14 m ²
3. Patch repairs over potholes					
with 20mm mix seal surface					
as per specification-					
	2	10		0.60m	12m ²
	5	7		0.70	24.5m ²
	10	8		0.50	40m ²
	6	9		0.60	32.40m ²
	2	12		0.70	16.80
					125.70m ²
4. Maintenance of bitumen					
mix seal surfacing on					
road as per specification					

Continuation

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Quantity Survey Station No. (3)					
Page (66) of T.M.B.					125.790 ^{m²}
5. Maintenance of cast works					
Stone Pipe Culvert					1 No.
6. Maintenance of Slab Type Culvert					2 No.
7. Maint. of Road Side					0.27 km
8. Maint of Quarry and KM Stone					0.33
9. Cultiv. of branches of tree and shrubs					3 No.
10. White Washing of Ponds walls and ed work					

Quantity vide Page (47) of T.M.B.					20.16 m ²
15/10/24					
J.E.					

ABSTRACT OF COST

1. Restoration of Rain cuts with soil masonry during					
Vide Page (65) of T.M.B.					
147.83 m ³ @ Rs. 380.58/m ³					Rs. 56259.2
2. Making of Berom / shoulder					
Stepping across Soil overlaps (66) of T.M.B.					609.14 m ²

Continuation
 @ Rs. 58.37/m² → Rs. 35556.2
 C/o Rs. 91815.2

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
				13/10/24	173169:
10. White washing of Pampal walls of CD work entrance.					
Quantity under Page - (67)					
of T.M.B. 20.16 m ²					
@ Rs. 16.65/m ²					Rs. 336.20
					Rs. 173505:
15/10/24				15/10/24	
15/10/24				15/10/24	
15/10/24				15/10/24	
Material Statement					
1. E.I.W. - 208.74 m ²					
2. Engr 51 - 6.79 m ²					
@ Rs. 450.34/m ²					
3. Portumeni, 0.060 m ²					
Portumen Available on site under Page (62) of M.B. No - 2692.					- 0.122 m ²
Portumen Consumed on site - 0.060 m ²					
Portumen Balance - 0.062 m ²					
15/10/24				15/10/24	
15/10/24				15/10/24	