

Baraon Mere Ke Pass to Hat Pokhar.

NDB (Bricks)

Schedule XLV-Form No. 134

PIRO

DIVISION

PIRO

SUB-DIVISION

Contractor Name: Shri Sanjay Kumar.

Measurement Book

App. No. → 48/SBD/mmasy/NDB Bricks.

NO. →

431

5th Year maintenance bill

36

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
NW:-	Baraon more ka				
	path to hat pokher.				
Agency:-	Sri Sanjay kumar.				
Apr No:-	48/S.B.D/M.M.H.S.Y.				
	NDB-bricks/2018-19.				
date of actual completion:-03/01/2020.					
date of M/s:-					
① Restoration of rain cut-off					
	6	4	1.80	0.30	$= 12.96 m^3$
	5	4	2.0	0.30	$= 12 m^3$
	2	5	1.0	0.30	$= 3 m^3$
	2	10	1.20	0.30	$= 7.20 m^3$
	2	4	1.10	0.30	$= 2.64 m^3$
	2	7	1.0	0.30	$= 4.20 m^3$
	Grand Total				$T = 42 m^3$
	30 mm W.B.M				$Lt = 32.35 m^3$
② Making up to berm/shoulder etc					
①	2	30	1.20		$= 72 m^2$
	3	30	1.0		$= 90 m^2$
	1	20	1.40		$= 28 m^2$
	10	1.20	1.0		$T = 190 m^2$
	10	1.20	1.0		$Lt = 179.72 m^2$
③ Repair of pot filled with					
	75 mm W.B.M - etc.				
	10	1.5	1.20		$= 18 m^2$

Continuation

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
④ patch repair over bituminous surface with 20 mm	@ A: 29.30 m ² , TMB. P-37				
	@ A: 359.93 m ² A: 10,545 = ∞				
⑤ cutting of branches of tree	Qty: - 29.30 m ² , TMB. P-37				
	① @ A: 213.04 m ² A: 6242 = ∞				
⑤ cutting of branches of tree	Qty: - 1 nos, TMB. P-37				
	@ A: 107.48 nos A: 107 = ∞				
	Total A: 38,443 = ∞				

Below 10%.

(A) A: 3845 = ∞

Total A: 34,598 = ∞.

Samp

C. K.
3/1/25
A: 203/01/25
I-E

Continuation