

का.से का.साम.:- NH 84 के कारी सा.व. मी.दा.द.भिन. ए.म.प.  
५५ का. सिमरि. M.M. ५५.५.

EX-1000 XCV-THO NA 1342

भा.य.यु.रु.न. सं. ३६०८.११७-१८

वि.व. म.व. व.व.

स.दा.मा.क. अभिमान. उ.द.व.न.जा.दा.८.

MAHAR P. W. D.

DIVISION

SHIP DIVISION

MAHAR P. W. D.



65

Scanned with OKEN Scanner

Sch. XLV-Form No. 134 64

| Particulars                           | Details of actual measurement |   |   | Contents of area |
|---------------------------------------|-------------------------------|---|---|------------------|
|                                       | No.                           | B | D |                  |
| 5th year meas.                        |                               |   |   |                  |
| N/N - NH-84 TO Kasisath Mahadev Tola. |                               |   |   |                  |
| A/A - Sri Rohit Kumar Singh.          |                               |   |   |                  |
| App. No. - 16/MMGSV/SC/SSD - 2017-18  |                               |   |   |                  |
| Date of app. - 23/06/2017             |                               |   |   |                  |
| Date of Comp. - 22/06/2018            |                               |   |   |                  |

Details of measurement

①. making of Berms/shoulder - do - do

|     |      |      |                         |                         |
|-----|------|------|-------------------------|-------------------------|
| 8 X | 8 X  | 18 X | 1.00                    | = 144.00 m <sup>2</sup> |
| 5 X | 22 X | 0.95 | = 104.50 m <sup>2</sup> |                         |
| 7 X | 16 X | 1.10 | = 123.20 m <sup>2</sup> |                         |
| 4 X | 12 X | 0.80 | = 38.40 m <sup>2</sup>  |                         |
| 3 X | 14 X | 0.90 | = 113.40 m <sup>2</sup> |                         |
| 6 X | 12 X | 0.95 | = 68.40 m <sup>2</sup>  |                         |

|     |      |      |                         |  |
|-----|------|------|-------------------------|--|
| 4 X | 20 X | 1.00 | = 80 m <sup>2</sup>     |  |
| 9 X | 16 X | 0.95 | = 136.80 m <sup>2</sup> |  |
|     |      |      | = 808.70 m <sup>2</sup> |  |

②. Restoration of drainage/berm shoulder - do - do - etc.

|     |     |        |      |                        |
|-----|-----|--------|------|------------------------|
| 1 X | 5 X | 2.50 X | 0.70 | = 8.75 m <sup>3</sup>  |
| 2 X | 3 X | 2.30 X | 0.35 | = 4.83 m <sup>3</sup>  |
| 1 X | 2 X | 2.50 X | 0.75 | = 3.75 m <sup>3</sup>  |
| 3 X | 7 X | 2.20 X | 0.30 | = 13.86 m <sup>3</sup> |
| 2 X | 5 X | 2.30 X | 0.65 | = 14.95 m <sup>3</sup> |
| 1 X | 9 X | 2.50 X | 0.75 | = 16.87 m <sup>3</sup> |
| 1 X | 4 X | 2.30 X | 0.75 | = 6.90 m <sup>3</sup>  |
|     |     |        |      | 69.91 m <sup>3</sup>   |

③. Patch repair with 20 mm. concrete

|     |     |      |                        |  |
|-----|-----|------|------------------------|--|
| 1 X | 9 X | 3.75 | = 33.75 m <sup>2</sup> |  |
|-----|-----|------|------------------------|--|

Continuation

