

4th years maintenance

64

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
1. Name of work:	Lalgumy Karkhiya				
	Bamark Tak Road Se Bhaywa				
	Pakar Bhargha Thakur K. Ghar				
	to Ram Gaudi ghat ewam				
	Ramkharwa Rameshwar Rai Ke				
	Ghar Tak				
2. Name of Agency:	Zija construction				
	2 Developers pvt. Ltd.				
3. Agreement No.	96/SBD/2019-20				
4. Actual dt. of completion:	25.12.2020				
	work done				

① Restoration of drain cuts
with 10% slope

1x	20.50	x 0.90	x 0.30 = 5.535
4x	10.50	x 0.90	x 0.30 = 11.34
8x	20.60	x 0.85	x 0.30 = 42.024
10x	20.70	x 0.75	x 0.32 = 49.68
8x	20.60	x 0.80	x 0.30 = 42.24
			39.552
			Σtg = 148.131m ³
			say 0.18 = 146.12m ³

② maintenance of earthen
shoulder slope

1x	20.60	x 0.90	= 18.54
1x	20.40	x 0.85	= 17.34
1x	30.0	x 0.90	= 27.0
2x	20.58	x 0.75	= 30.87
4x	10.85	x 0.75	= 32.55

Continuation Σtg = 126.30m²

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
			BFR	242885	= 00
⑥ maintenance of slab					
7 type culvert - duplex					
Qty = 7.0 nos vide TMB					
page (67)					
⑦ 2273 = 47/each					Rs 15914 = 00
⑧ maintenance of road					
8 879m - duplex					
Qty = 2.08 km vide					
TMB page (67)					
⑨ 1054 = 28/Km					Rs 2193 = 00
(8/9) maintenance of					
2.08 km & km stone					
also duplex					
Qty = 2.08 km vide					
TMB page (67)					
⑩ 711 = 43/Km					Rs 1480 = 00
					Rs 262472 = 00
1% Labour cess (+) Rs					262500
12% GST					Rs 31497 = 00
					Rs 296594 = 00
Less 10.0% below CR					Rs 29659 = 00
					Rs 266935 = 00
RM 25.12.2027					
25.12.2027					

Continuation