

Particulars

Details of actual measurement

Contents of area

No. L. B. D.

4th Year maintained

Name of work - 5 years routine maintenance

of road from Gauri to Nath

(Kushwaha tola).

Contractor - Shailendra Kumar Tiwari.

Agreement No - S.B.D-20/2019-20

Actual date of completion - 6/12/20

D.O. Entry - 16/12/24

Measurement Details

① Restoration of rain cut /- do

$$2 \times 1000 \times 1.125 \times 1.25 \times 0.30 \times 9.60 = 81 \text{ m}^3$$

② Marking up Boring / Shoulder

$$2 \times 1000 \times 1.125 \times 1.25 \times \frac{16}{100} = 450.4 \text{ m}^2$$

③ Repair of Pot hole filled - do

$$850 \text{ m} \times 3.75 \times 1.25 \times \frac{2}{100} \times 0.075 = 5.97 \text{ m}^3$$

④ Patch repair over Pot hole - do

$$850 \times 3.75 \times 1.25 \times \frac{2}{100} \times 1.0 = 79.687 \text{ m}^2$$

⑤ Patch repair on B.T. surface

$$850 \times 3.75 \times 1.25 \times \frac{2}{100} = 79.687 \text{ m}^2$$

⑥ Maintenance of C/D - do = 0.2 Nos

⑦ Maintenance of Road signs - do = 0.15 Km

⑧ Maintenance of 200m - do = 0.18 Km

⑨ cutting of branches of tree - do = 2000 Nos

⑩ cutting of shrubson - do = 10 Nos

⑪ trimming of grass - do = 5.63 m²

⑫ white washing - do - Parpet =

$$2 \times 21 \text{ m}^2 = 42 \text{ m}^2$$

Continuation

21

16/12/24
T.E.

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
(i) Cutting of shrubs - do of y side TMB P-(78) item (10)	10 Nos	②	R. 6.54/m ²		R 65=0
(ii) Trimming of grass - do of y side TMB P-(78) item (11)		5.63 m ²	② R. 2.18/m ²		R 12=0
(iii) white washing on Parapet - do of y side TMB P-(78) item (12)	42 m ²	② R. 16.85/m ²			R 699.20
			Total = R. 18119.80		
Less 10% below				E/R 18110=0	
			Payable	R. 16307.80=0	

8
16/12/24
26.