

ਦਾਖਲ ਕੀਤੀ ਗਈ ਹੈ ਅਤੇ ਇਸ ਦੀ ਸਹਿਮਤੀ ਮਿਲੀ ਹੈ।

MMGSY (5E)

# Schedule XLV-Form No. 134

ਦਾਖਲ **DIVISION**

216 **SUB-DIVISION**

# MEASUREMENT BOOK

1562

ਦਾਖਲ ਕੀਤੀ ਗਈ ਹੈ ਅਤੇ

43 SB2  
2020-21



Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
③ Repair to potholes and removal of loose materials - all up					
4251 m <sup>2</sup> VTRABD (46)					
① 281=73/m <sup>2</sup>					11926=
④ Maintenance of C.D. Work					
4.9 km VTRABD (46)					
① 1130=57/each					4523=
⑤ Maintenance of Road					
5.7 km					
0.185 km VTRABD (46)					
① 1080=23/km					200=
⑥ Maintenance of 200mm 2.00 Stone - all up					
0.23 km VTRABD (46)					
① 482=55/km					111=
⑦ Cutting of branches/trees and stumps					
5.0 km VTRABD (46)					
① 100=25/each					505=
⑧ Cutting of stumps from road					
20.0 km VTRABD (46)					
① 6=23/m					135=
⑨ Trimming of grass/maize					
49.50 m <sup>2</sup> VTRABD (46)					
① 2=24/m					111=
⑩ Water Wash of Street					
83.26 m <sup>2</sup> VTRABD (46)					
① 16=34/m					1369=

Continuation

Less 10% below As per spec - 80054 =  
8005 =

12-02-23  
JF

Rs 70  
672049 =



39092

Particulars	Details of actual measurement				Center of are
	No.	L.	B.	D.	
① Maintenance of 1/30m/					
Shoulder cut in					
6/2.0m VTMBP					
② 66=55/m					34609
③ Repair of Trench with					
20000ms MS - all up					
56.68m		85.68m			
④ 281=73/m					24139
⑤ Maintenance of 40 Wm					
4.0m VTMBP					
⑥ 1130=60/each					4523
⑦ Maintenance of 200m					
0.22 km VTMBP					
⑧ 1080=23/Km					238=0
⑨ Maintenance of 200m					
1 km stone					
0.20 km VTMBP					
⑩ 482=55/1km					130=2
⑪ (I) Cutting of branches/					
9 trees a of 8cm					
4.0ms VTMBP					
⑫ 100=59/each					404=0
(II) Cutting of Stumps					
from Railway					
21.0m.s VTMBP					
⑬ 6=23/each					141=2
(III) Pruning of grass and					
Woods					
83.26m <sup>2</sup> VTMBP					
57.26m					
⑭ 2=24/m <sup>2</sup>					116=
⑮ White Wash of parapet					
2 faces - all					
83.76m VTMBP					
⑯ 16=34/m <sup>2</sup>					1368=
Loss 10/below 15 per 100m					104.881=1
					104.88=2
					94393=

Continuation

26-08-23

# 3rd year Maintain Bill

54

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Content of area
	No.	L.	B.	D.	
N/W - Buxar Dhamkozi Basara					
Kala Road to Jhaukha Vidau					
Tola Talu					
Agency - Sri Rohit Krodha					
Ag No - 43870/20-21					

## ① Restoration of raincuts

8 x 15m x 1.12 x 0.30 = 40.32m <sup>3</sup>
5 x 30m x 1.10 x 0.30 = 49.50m <sup>3</sup>
4 x 18.0m x 1.15 x 0.30 = 24.84m <sup>3</sup>
5 x 20m x 1.05 x 0.30 = 31.50m <sup>3</sup>
Total = 146.16m <sup>3</sup>
Less = 146.20m <sup>3</sup>

## ② Maintenance of shoulders

3 x 30m x 1.15 = 172.50m <sup>2</sup>
8 x 17.0m x 1.10 = 149.60m <sup>2</sup>
6 x 25m x 1.125 = 168.75m <sup>2</sup>
4 x 21.00m x 1.12 = 94.08m <sup>2</sup>
7 x 20m x 1.0 = 140m <sup>2</sup>
8 x 12.0m x 1.05 = 100.80m <sup>2</sup>
Total = 825.73m <sup>2</sup>
Less = 841.3m <sup>2</sup>

## ③ Path hole repair work

3 x 4.80 x 1.35 x 0.075 = 1.458m <sup>3</sup>
5 x 3.70m x 1.60 x 0.075 = 2.22m <sup>3</sup>
4 x 4.90 x 2.10 x 0.075 = 3.087m <sup>3</sup>
5 x 4.60m x 2.20 x 0.075 = 3.795m <sup>3</sup>
2 x 2m x 1.0 x 0.075 = 0.30m <sup>3</sup>
Total = 10.86m <sup>3</sup>

Continuation

