

Sch.XLV-Form No. 134

Particulars	Details of actual measure				Contents of area
	No.	L.	B.	D.	
ON 12 year maintenance Bill					
Name of work - m m c s Road					
to Numbur 10/10					
Name of Agency - Khushi Electric					
Name of Agreement - O/S B D 2023-24					
Actual Date of completion 14/11/23					

(iii) Restoration of rain cuts

$4 \times 10.2 \times 0.6 \times 0.3 =$	$7.344 m^3$
$3 \times 9.8 \times 0.8 \times 0.3 =$	$7.056 m^3$
$2 \times 12.3 \times 0.6 \times 0.3 =$	$4.428 m^3$
$8 \times 9.5 \times 0.5 \times 0.3 =$	$11.40 m^3$
$6 \times 9.2 \times 0.5 \times 0.3 =$	$8.28 m^3$

(iv) maintenance of earthen shoulder

$6 \times 8.3 \times 0.5 =$	$24.90 m^2$
$9 \times 7.1 \times 0.6 =$	$38.34 m^2$
$8 \times 10.3 \times 0.150 =$	$12.36 m^2$
$6 \times 9.3 \times 0.3 =$	$16.74 m^2$
$5 \times 12.3 \times 0.6 =$	$36.9 m^2$
$9 \times 12.5 \times 0.39 =$	$43.875 m^2$
$8 \times 12.3 \times 0.40 =$	$39.36 m^2$
	Total = $212.475 m^2$

(313) Repair of Pot holes in S S Road

$6.3 \times 1 =$	$6.3 m^2$
$9.9 \times 9.4 \times 0.8 =$	$7.92 m^2$
$4 \times 0.7 =$	$2.8 m^2$
	Total = $17.02 m^2$

Continuation

Scanned with CamScanner