

415 years Mantam Prii
78

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Name of work - Dug out katrai Road					
To 2 to Dharan - keast					
Mushon and yadav Lok					
Agency - Sri Sanjay Kumar					
Ag No - 16 SPD/19-20					
Work done					
① Restoration of drain - do -					
$10 \times 30 \times 1.125 \times 300 =$					$101.25 M^3$
$10 \times 30 \times 1.125 \times 300 =$					$101.25 M^3$
$10 \times 30 \times 1.125 \times 300 =$					$101.25 M^3$
$1 \times 12 \times 1.125 \times 300 =$					$4.05 M^3$
					$307.80 M^3$
② Make up curb - do -					
$10 \times 30 \times 1.0 =$					$300.00 M$
$10 \times 30 \times 1.0 =$					$300.00 M$
$10 \times 30 \times 1.0 =$					$300.00 M$
$10 \times 30 \times 1.0 =$					$300.00 M$
$10 \times 30 \times 1.0 =$					$300.00 M$
$7 \times 30 \times 1.0 =$					$210.00 M$
					$1710.00 M^2$
③ Repair of pot hole - do -					
$6 \times 30.0 \times 1.60 \times 0.075 =$					$21.60 M^3$
$1 \times 13.40 \times 1.60 \times 0.075 =$					$1.60 M^3$
					$23.20 M^3$
④ Patch repair of -					
as vide (3) = $23.20 / 0.075$					
					$309.38 M^2$
⑤ Patch repair over bitumen - do -					
vide (4) = $309.38 M^2$					

Continuation

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
(10) Pully gashab - do w/room - (29)					
ab = 38.00 m					
Ch 6754 m				R 24924	
(11) Pully gashab - w/room					
P - (29)					
ab = 21.38 m					
Ch 218 m				R 4720	
(12) Whib w/room - do					
P - (29) ab = 126.00 m					
Ch 16 = 65 m				R 209824	
				R 67683124	

Less 10% below C) R 6778324

R 69904824

Jul
31/12/2024

Jul
31/12/24

Q