

2nd year maintenance

46

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
None of north - point of roof					
from 1052 to 1053 P. 1051					
Agency - Roshan Singh					
agreement no - 20230/20-21					
Date of work -				11.12.2020	
Actual completion.				25.12.2020	

Record of Entry

- (1) Restoration of soil
cutting soil

6x5.80x1.10x0.30:	11.48
7x4.90x1.20x0.30:	13.22
7x6.60x0.90x0.30:	12.42
8x5.80x0.80x0.30:	11.14
6x9.20x0.95x0.30:	16.59
8x5.40x0.75x0.30:	9.72
7x4.50x0.85x0.30:	10.33
Total:	84.96

- (2) Point of earthwork
shoulder -

2x9x8.90x0.90:	144.18
2x16x5.80x0.85:	152.26
2x12x8.90x0.95:	152.32
2x6x1.75x0.60:	12.60

Total 421.86

Continuation

Continuation