

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
4th year maintenance Bill :-					
Name of Work :- Kachi Pakki Path Ramchar					
dya Malang Althanti Basanti					
Purvi tola MMGSY					
Agency :- Krishvita Infrastructure Pvt. Ltd.					
Jagdishpur vaichali					
Agreement No - 13/SBD/2019-2020					
Date of Work order - 08/03/2019					
Date of completion - 07/03/2020					
1/15.1 Generation of Rain cuts :-					
4 x 12.3 x 0.8 x 0.3 =					9.888 m ³
6 x 12.5 x 0.9 x 0.3 =					20.25 m ³
5 x 12.6 x 0.8 x 0.3 =					15.12 m ³
7 x 10.4 x 0.7 x 0.3 =					15.288 m ³
6 x 9.9 x 0.9 x 0.3 =					16.038 m ³
5 x 8.2 x 0.8 x 0.3 =					9.84 m ³
Total Qty =					86.424 m ³
2/15.2 Maintenance of earthen shoulder :-					
4 x 7.3 x 0.6 =					17.52 m ²
3 x 8.3 x 0.7 =					17.43 m ²
4 x 9.75 x 0.7 =					27.3 m ²
10 x 16.5 x 0.9 =					148.5 m ²
8 x 10.3 x 0.7 =					57.68 m ²
5 x 12.35 x 0.6 =					55.05 m ²
6 x 15.4 x 0.8 =					73.92 m ²
4 x 12.1 x 0.9 =					43.56 m ²
5 x 11.8 x 0.8 =					47.2 m ²
Continuation					
Total Qty =					488.16 m ²

Material used	Quantity
FORTH LIDYK	$= 159.648 \text{ m}^3$
Bitumen	$= 375 \text{ kg}$
stone chips	$= 5.505 \text{ m}^3$

Scanned with CamScanner