

Sch. XLV-Form No. 134

$\text{Area} = 39.38 \text{ m}^2$
 @ R 109.01/m² R/16.107 = W
 ④ pot - holes repaired
 20 mm thick premix carpet
 X.T. M.B & P - 61
 $\text{Area} = 39.38 \text{ m}^2$
 @ R 310.40/m² R/12.224 = W
 ⑤ patch repaired
 20 mm thick premix carpet
 X.T. M.B & P - 62
 $\text{Area} = 39.38 \text{ m}^2$
 @ R 330.24/m² R/13.005 = W

Continuation

Continuation
C-1044 R 99, 633 = W

D.F. R, 99, 633 = 0

65

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
⑥ Maintenance of Hume					
pipe cut-off					
V.T. M.B & P-62					
Qty - 1 Nos					
① R, 1109.67/each R,					1110 = 0
⑦ Maintenance of road					
signages.					
V.T. M.B & P-62					
Qty - 0.23 K.m					
① R, 1066.50/each R,					245 = 0
⑧ Maintenance of K.M					
& 200m post					
V.T. M.B & P-62					
Qty - 0.28 K.m					
① R, 641.62/K.m R,					180 = 0
⑨ Cutting of Branch					
& 400m shrubs					
V.T. M.B & P-63					
Qty - 1 Nos					
① R, 105.39/each R,					105 = 0
⑩ Cutting of shrubs					
from roadway cutting					
V.T. M.B & P-63					
Qty - 5 Nos					
① R, 6.47/each R,					32 = 0

Continuation

C.O. Total - R 1,01,305 = 0

66

Sch. XLV-Form No. 134					Contents of area
Particulars	Details of actual measurement				
	No.	L.	B.	D.	

Continuation

P.T.O