## कार्यपालक अभियंता का कार्यालय ग्रामीण कार्य विभाग, कार्य प्रमंडल, शिवहर।

## हमारा बिहार हमारी सड़क प्रतिवेदन

Feedback ID No.-18522347500363

Active designation of the region of the regi		
प्रश्न	संबंधित पथ का नाम	उत्तर
The road is completely full of potholes, the condition of the road is so bad that people have fallen many times, the 3 km long road which should take 10 minutes takes 1 hour, the entire road has been ruined by laying bricks on it and it has been ruined, If it rains then the way to come and go gets closed	Kahatarawa	प्रश्नाधीन पथ शीर्ष MR-3054 अंतर्गत स्वीकृत फतेहपुर से कौड़िया लालगढ़ पथ से संबंधित है। पथ की लंबाई 8.00 कि०मी० है। उक्त पथ के अनुरक्षण हेतु संवेदक को अनेको बार मौखिक एवं पत्र के माध्यम से निर्देशित किया गया था परंतु पथ का अनुरक्षण नहीं किये जाने के कारण संवेदक के एकरारनामा को दिनांक-26.09.2024 को विखंडित कर दिया गया है एवं निबंधन को काली सूची में शामिल करने हेतु उच्चाधिकारी को अनुशंसा कर दी गई है। वर्तमान में पुनरीक्षित प्राक्कलन तैयार कर स्वीकृति हेतु विभाग को समर्पित किया गया है।

134.06.

कार्यपालक अभियंता, ग्रामीण कार्य विभाग, कार्य प्रमंडल, शिवहर।