

**कार्यपालक अभियंता का कार्यालय**  
**ग्रामीण कार्य विभाग, कार्य प्रमण्डल, बेलसंड**

पत्रांक— 1092

दिनांक— 02/07/2025

प्रेषक,

कार्यपालक अभियंता,  
ग्रामीण कार्य विभाग,  
कार्य प्रमण्डल, बेलसंड

सेवा में,

अपर मुख्य कार्यपालक पदाधिकारी —सह—सचिव,  
बिहार ग्रामीण पथ विकास अभिकरण,  
ग्रामीण कार्य विभाग, बिहार, पटना।

विषय— RRSMP(GEN) के क्रियान्वित पथों के भुगतान हेतु अधियाचना के संबंध में।

महाशय,

उपर्युक्त विषयक प्रासंगिक पत्र के संबंध में कहना है कि कार्यप्रमण्डल बेलसंड अन्तर्गत RRSMP (GEN) के पथ में पूर्ण कराये गये कार्यों का भुगतान हेतु अधियाचना विहित प्रपत्र में तैयार कर आवश्यक कार्रवाई हेतु समर्पित की जाती है।

सूचनार्थ एवं आवश्यक कार्रवाई हेतु समर्पित।

अनु०— 1. अधियाचना विहित प्रपत्र में।

विश्वासभाजन

02/07/25  
कार्यपालक अभियंता,  
ग्रामीण कार्य विभाग,  
कार्य प्रमण्डल, बेलसंड  
2/7/25

**Aquisition Format for Scheme RRSMP[Gen]**

**Name of the Works Division- RWD, Works Division-Belsand**

Sl. No.	Package No	Project ID as per MIS	Name of Road	AA Length (in km)	Administrative Approval (construction work) Amount (in Lakh)	Agreement (construction work) Amount (in Lakh)	Agreement No. & Date	Date of Completion as per Agreement	Actual Date of Completion	Work Status (WB/M/SDB C etc.)	Value of IRI (in mm/km)	Thickness of Bitumen Layer (in mm)	Value of Bitumen Content (in %)	Total Previous Allotted Amount (in lakh)	Up to Date expenditure as per MIS (in Lakh)	Value of Work Done (in Lakh)	Current Demand (in lakh)	Remarks
1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19
1	RRSMP/24-25 Belsand/04	6160800350062	Dev Narayan Ray's House To Manik Chowk To Dhanpura Path Near Pramod Ray's House	0.750	43.21900	45.56724	03MBD/2025-26 19.05.2025	18-05-2026	-	PCC	-	-	-	0.00000	0.00000	40.09282	40.09282	In progress
2	RRSMP/24-25 Belsand/04	6160800350068	Repair of road from Gangewar to Thakali	3.700	333.03700	342.00054	03MBD/2025-26 19.05.2025	18-05-2026	-	PCC	-	-	-	0.00000	6.45744	109.12220	109.12220	In progress
3	RRSMP/24-25 Belsand/04	6160800350069	Repair of road from Vishunpur to Mahindwara	1.150	106.20800	108.73638	03MBD/2025-26 19.05.2025	18-05-2026	-	PCC	-	-	-	0.00000	0.00000	38.36049	38.36049	In progress
4	RRSMP/24-25 Belsand/03	6160800350021	FROM THE HOUSE OF UGRASEN MAHTO TO PRIMARY SCHOOL TO KANHOLI VILLAGE ROAD	1.800	167.03400	140.39420	02MBD/2025-26 16.05.2025	15-05-2026	-	PCC	-	-	-	0.00000	0.00000	70.22006	70.22006	In progress
5	RRSMP/24-25 Belsand/03	6160800350025	PARSURAM MIDDLE SCHOOL TO SUNDERGAMA	1.260	115.67600	97.67117	02MBD/2025-26 16.05.2025	15-05-2026	-	WBM	-	-	-	0.00000	0.00000	25.93778	25.93778	In progress
6	RRSMP/24-25 Belsand/03	6160800350031	Chhotia Parsauni To L031	0.950	64.20000	61.86024	02MBD/2025-26 16.05.2025	15-05-2026	-	WBM	-	-	-	0.00000	0.00000	8.18052	8.18052	In progress

It is certified that Physical & Financial Progress has been updated in MIS.

Note:-

1. Above Signed Copy along with Forwarding Letter & Utilization Certificate must be uploaded in MIS.

Divisional Accounts Officer  
RWD, Works Div. Belsand

Executive Engineer,  
RWD, Works Div. Belsand

**GENERAL FINANCIAL RULES 2017**

**Ministry of Finance**

**Department of Expenditure**

**GFR 12-B**

**[SEE Rule 256(2)]**

**FORM OF UTILIZATION CERTIFICATE**

- (1) Certified that out of the Loan of RS 19141645, Sanctioned under RRSMP(GEN). Letter no-39 dated 21.05.2025, in favour of Executive Engineer, RWD Works Division Belsand, during the year 2025-26, an amount of Rs 19141645, has been utilized for the purpose for which it was sanctioned, and that the balance of Rs 00000, remaining unutilized at the end of the year 00000 has been surrendered to the Government (vide No....., dated.....)/will be adjusted towards the loan payable during the next financial year.
- (2) Certified that I have satisfied myself that the conditions on which the loan was sanctioned have been duly fulfilled/are being fulfilled and that I have exercised the following checks to see that the money was actually spent for the purpose for which the loan was made.

**Kinds of checks exercised**

1. Works have been supervised by Executive Engineer/ Superintending Engineer.
2. Periodical inspection has been conducted by Executive Engineer/ Superintending Engineer.
3. Construction material have been tested.
4. Measurements have been recorded in the MBs and test check conducted by the Assistant Engineer/Executive Engineer.
5. All other codal formalities have been observed.

  
D.A.O

R.W.D Works Division Belsand

  
Executive Engineer

R.W.D Works Division Belsand