

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
<u>ON 2nd year maintenance bill :-</u>					
<u>Name of work :- construction of Road from</u>					
<u>PAKDI mukhaya sadak pramod chakhatav</u>					
<u>Kr ghay to Bodha Bayha cheddira cheni</u>					
<u>take under MMGSY (S.C)</u>					
<u>Name of Agency :- available infrastructure</u>					
<u>Pvt Ltd.</u>					
<u>Agreement No :- 76 (R.D) - 2020-21</u>					
<u>Date of started :- 24-09-2021</u>					
<u>Date of completion :- 23-09-2021</u>					
<u>Actual date of completion :- 20-9-2021</u>					
<u>① Restoration of ram cuts</u>					
	5	10.3	0.8	0.3	$= 12.36 m^3$
	6	8.3	0.9	0.3	$= 13.446 m^3$
	8	11.2	0.8	0.3	$= 24.192 m^3$
	5	10.3	0.6	0.3	$= 9.81 m^3$
	10	10.8	0.9	0.3	$= 29.16 m^3$
	8	12.9	0.8	0.3	$= 24.768 m^3$
					Total $= 113.736 m^3$
<u>② Maintenance of Earthen shoulder</u>					
	5	7.6	0.6		$= 22.80 m^2$
	6	10.7	0.7		$= 44.94 m^2$
	8	9.75	0.7		$= 54.6 m^2$
	9	16.5	0.9		$= 133.65 m^2$
	10	12.5	0.7		$= 87.5 m^2$
	8	18.1	0.6		$= 88.88 m^2$
	7	14.2	0.8		$= 79.52 m^2$
	16	12.1	0.9		$= 108.90 m^2$
					Total $= 618.79 m^2$

Continuation

Continuation