

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
<u>3rd Year Maintenance Bill</u>					
Name of work - Mathiya to Sital Rai Mathiya Tola					
Authority- E.E RWD Bagaha-1					
Agency - M/s Dharma Construct.					
Agg. No-04 SBD/2021-22					
D/S- 15/04/2021					
D/C- 14/01/2022					
A/D/C- 12/01/2022					

① Maintenance of Earthen Shoulder with Soil:-

$$30 \times 5.80 \times 1.05 = 182.70 \text{ m}^2$$

$$23 \times 5.75 \times 1.00 = 132.25 \text{ m}^2$$

$$314.95 \text{ m}^2$$

② Maintenance of Road Signs:-

$$1 \times 0.4 \text{ km} = 0.4 \text{ km}$$

③ Maintenance of KM and 200 m stone:-

$$1 \times 0.80 \text{ km} = 0.80 \text{ km}$$

④ Road Marking with hot applied thermoplastic Paint etc.

$$2 \times 800.00 \times 0.10 = 160.00 \text{ m}^2$$

Ambar
15/01/22
S.E.

Raj k
15/01/22
T.S.

Aravind k
15/01/22
or

Continuation

PTO

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
<u>ABSTRACT OF COST</u>					
(1/2) Maintenance of Earthen Shoulder with Soil :-					
Qty Vide Page No-(46) of TMB					
314.95m ² @ 60.48					
= 19048 = 00					
(2/3) Maintenance of Road Signs :-					
Qty Vide Page No-(46) of TMB					
0.4 km @ 1104.59					
= 442 = 00					
(3/10) Maintenance of 200m and km. Stones :-					
Qty Vide Page No-(46) of TMB					
0.80 km @ 725.65					
= 5801 = 00					
(4/11) Road Marking with hot applied thermoplastic Paint etc. :-					
Qty Vide Page No-(46) of TMB					
160.00m ² @ 721.95					
= 115512 = 00					
= 135583 = 00					
Add 12% C.S.T = 16270 = 00					
Add 1% L.Corr = 1356 = 00					
= 153209 = 00					
Less 15.02% Below = (-) 23012 = 00					
= 130197 = 00					

Amor
15/01/25
5.6

Raj
15/01/25
Continuation

Rad
15/01/25
OK