

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
3rd year Maintenance					
Name of Work - Paroraha to					
Badai tola Paroraha					
Authority - E. E RWD					
Bagaha - I					
Agency - Deepchand Chauhan					
Agg No - 10 SBD/2021-22					
D/S - 04/05/2021					
Extended/D/C - 04/05/2022					
A/D/C - 15/04/2022					

① Restoration of rain Cuts with Soil:-

$$21 \times 1.90 \times 1.75 \times 0.3 = 20.95 \text{ m}^3$$

$$16 \times 1.90 \times 1.70 \times 0.3 = 15.50 \text{ m}^3$$

$$= 36.45 \text{ m}^3$$

② Maintenance of Earthen Shoulder:-

$$25 \times 5.50 \times 1.0 = 137.5 \text{ m}^2$$

$$15 \times 5.30 \times 0.95 = 75.52 \text{ m}^2$$

$$10 \times 5.10 \times 0.90 = 45.90 \text{ m}^2$$

$$= 258.92 \text{ m}^2$$

③ Repair of pot holes by WBM:-

$$15 \times 1.40 \times 0.95 = 19.95 \text{ m}^2$$

$$10 \times 1.25 \times 0.90 = 11.25 \text{ m}^2$$

$$5 \times 1.10 \times 0.90 = 4.95 \text{ m}^2$$

$$= 36.15 \text{ m}^2$$

Continuation

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
<u>ABSTRACT OF COST</u>					
<u>(1) Restoration of main cuts with Soil:-</u>					
Qty Vide P. No - (68) of TMB					
= 36.45 m ³ @ 404.06					
= 14728 = 00					
<u>(2 1/2) Maintenance of earthen Shoulder:-</u>					
Qty Vide P. No - (68) of TMB					
= 258.92 m ² @ 60.48					
= 15659 = 00					
<u>(3 1/3) Repair of pot holes by WBM:-</u>					
Qty Vide P. No - (68) of TMB					
= 36.15 m ³ @ 468.99					
= 16954 = 00					
<u>(4 1/4) Patch repair with 20mm Premix Carpet:-</u>					
Qty Vide P. No - (69) of TMB					
= 36.15 m ² @ 295.36					
= 10677 = 00					
<u>(5 1/8) Maintenance of CD (Slab Culvert)</u>					
Qty Vide P. No - (69) of TMB					
= 1 no @ 2394.96					
= 2395 = 00					
<u>(6 1/9) Maintenance of Road Signs:-</u>					
Qty Vide P. No - (69) of TMB					
= 0.33 Km @ 1104.59					
= 367 = 00					
<u>(7 1/10) Maintenance of 200m and Km stone:-</u>					
Qty Vide P. No - (69) of TMB					

Continuation

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
					= 0.665 km @ 725.65
					= 483 = 00
(8/11) Cutting of branches of tree and Shrubs :-					
Qty Vide P. No - (69) of TMB					
					= 2 Nos @ 113.99
					= 228 = 00
(9/11) Cutting of Shrubs :-					
Qty Vide P. No - (69) of TMB					
					= 6 Nos @ 6.98
					= 42 = 00
(10/11) Trimming of grass and weeds :-					
Qty Vide P. No - (69) of TMB					
					= 577.80 m ² @ 2.33
					= 1346 = 00
(11/11) Maintenance of trees by road sides :-					
Qty Vide P. No - (69) of TMB					
					= 50 Nos @ 590.01
					= 29,500 = 00
(12/11) Road Marking with hot applied thermoplastic Paint :-					
Qty Vide P. No - (69) of TMB					
					= 133.00 m ² @ 721.95
					= 96019 = 00
Total					= 188398 = 00

Continuation

PTO.

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	

Handwritten notes on grid paper:

- Top left: $\frac{1}{2} \text{ mm}$, 18/04/25, 5.6
- Top right: $\frac{1}{2} \text{ mm}$, 18/04/25, 7.5
- Bottom right: $\frac{1}{2} \text{ mm}$, 18/04/25, 7.5

E/W	62	m ³
Chup	1	m ³
Bitumen	0.089	m ³
Emulsion	0.077	m ³

~~Revised~~
18/04/25
J.E.

~~Revised~~
28/4/25
TS

~~Revised~~
12/04/25
J.E.

Continuation