

HEAD - MR-3054

~~DRKALINEA~~

DRKALINEA - MR-N/23-24 - Sima Baktiyar pur - 10

Schedule XLV-Form No. 134

NAME of work - Repairing Bag 200 To Angora Seema
Wdg. Sygas pur Baktiyar pur Baktiyar pur 10/19

R.W.D. Baktiyar pur DIVISION

Simam Baktiyar pur

R.W.D. Baktiyar pur SUB-DIVISION

Simam Baktiyar pur

Measurement Book

955

Name of Contractor - Baktiyar pur Baktiyar pur Baktiyar pur

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
					BF-8 A 41, 21, 618 m
Add 18% CST					25,50,601 m
Add 1% CC					1417000=00
Add 8% fee					144449=00
					167362=00
					R 170,31,587=00
					17006755=00
Less 18.5% Slab					31,52,5672 m
					3147951=00
					R 138,79060=00
					13858804=00
Less 8% Pw					11,32,03229=00
Work has been completed as per specification					R 6,78,811=00
					655575=00
					10/12/25 A.E.
					10/16/25
					66