

3rd year maintenance

Sch. XLV-Form No.134

26

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
N/W:- Main & Road from Purnachya					
Vijaya road to Rajwari Kher and					
Math 2019 ward No-1					
MMSY 30'					
Block — Ghansalen					
Agency:- M/s Shandilya Enterprises.					
Gyatsi Hayer Motikani					
E. Chafan.					
Assessment No:- 36 MBO/2020-21					
Actual Date of comp:- 25-3-2022					

Abstract of cost

1/1

Restoration of Road

cut with soil

Q.

P-26

115.38 m² @ 9.386.14 9. 44555.2

2/2

Making up of shoulder

filling

Q.

P-27

780.86 m² @ 9.57.56 9. 40341.2

3/3

Repair of Pot holes

by filling

Q.

P-28

114.57 m² @ 9.419.32 9. 47999.2

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
4/5 Patch Repair over bituminous surf					
		P. 28			
114.47 m ² (9) 303.87				9	34784
5/10 Main 15 ft deep ditches stone					
		P. 28			
1.78 km (9) 702.29				9	1250
6/9 Main 15 ft deep ditches by way					
		P. 28			
0.89 km (9) 1077.81				9	959
7/11 (I) Cutting of branch of stone					
		P. 28			
4 NO (9) 109.24				9	439
8/11 (II) Cutting of shrubbery from P. way					
		P. 28			
17 NO (9) 6073				9	114
9/11 (III) Trimming of grass and weeds					
		P. 28			
1831.50 m ² (9) 2.24				9	4103
10/11 (IV) Main 15 ft deep by the road side					

Sch. XLV-Form No.134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
		P. 28			
162 NO ①	1	574.05		9	92996.2
11/11 ①		Piv and app 28.01			
		with water bound			
		P. 28			
30.40 m ² ②	9	90.98		2	2766.2
12/11 ⑤		Piv and app 1.10			
		app Road Marking			
		P. 30			
356.00 m ² ③	9	735.44		1	261817.2
					1
				Q	532123.2

At 1 G ST ④	12.1		9	63855.2
At 1.00 ④	1.7		9	5321.2
At 1 S. R.			9	208500.2
			2	601507.2
len 0.03 -1. below ⑤				180.2
			9	601327.2

2618125
 2E