

પ્રિપ્રોગ્રસીવ સી

M.B.No-3173

Schedule XLV Form No. 134

વનપુરો સે વનપુરો દરેજાગરોના નકદ ૫૫/

પ્રિ. નો 23580/2019-28.

સી. 2022 કુમાર સિદ્ધ

DIVISION

સી. સાલો 2020 પ્રસન્ન યાદવ સુદ 10 આદિ

SUB-DIVISION

સુદ 10 આદિ

MEASUREMENT BOOK

M.B.No-3173

5th year maintenance bill

62

Sch. XLV—Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
N/W — Bampurua Se Bampurua					
Harujan told,					
Agency — Shambhu Kr Singh					
Agreement No. — 235AD/19-20					
Work started — 18/2/19					
ADOC — 80/5/20.					
① Reformation of drains.					3
$7 \times 3.88 \times 1.25 \times 0.300 = 3.96 \text{ M}^3$					
$7 \times 3.95 \times 1.5 \times 0.300 = 9.54 \text{ ''}$					
$9 \times 3.90 \times 1.20 \times 0.300 = 12.54 \text{ ''}$					
$5 \times 3.60 \times 1.15 \times 0.300 = 9.24 \text{ ''}$					
$7 \times 4.15 \times 1.20 \times 0.300 = 10.46 \text{ ''}$					
$6 \times 4.80 \times 1.25 \times 0.300 = 10.80 \text{ ''}$					
$10 \times 5.77 \times 1.25 \times 0.300 = 21.60 \text{ ''}$					
$7 \times 7.13 \times 1.25 \times 0.300 = 18.72$					
					10.96 M ³
					Qty of sand 100.24 M ³ .
② Making up shoulder.					
$22 \times 12.87 \times 1.25 = 354.38 \text{ M}^2$					
③ Repair of path hole with 25 mm					
K.P.M.					
$45 \times 19.45 \times 1.25 \times 0.075 = 82.03 \text{ M}^3$					3
④ Patch repair over path hole					
with 20 mm m. Carpet.					
$13 \times 5.048 \times 1.25 = 82.03 \text{ M}^2$					
⑤ Patch repair over bitumin surface. Qty same as					
for item No. — ④					82.03 M ²
⑥ Maintenance of CD house					
pipe continuation					3 No.

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
① Maintenance of road Segm. 0.170 km.					
② Maintenance of 20m x km segm. 0.260 km					
③ Cutting of branches of trees — 2 NO.					
④ Cutting of shrubs. 7 NO.					
⑤ Mowing of grass 18 NO.					
⑩ Road mactening. 2x44x25x0.100 = 220M ²					
⑪ White washing — 63M ²					
JE	25/3/75	JE	25/3/75	AB	
mahal statement					
Gravel — 100.20M ³					
Stone metal — 117.30M ²					
Stone chips — 4.43M ³					
Coarse Sand — 1.48M ³					
JE	25/3/75	JE	25/3/75	AB	

Continuation

Abstract of Cost

64

Sch. XLV—Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
① Restoration of drains.					
Drain (62) 100 24M ³					
@ Rs 65.25/M ³					Rs 6612=00
② Making up shoulder.					
Drain (62) 354.38M ²					
@ Rs 54.16/M ²					Rs 19193=00
③ Repair of pothole with 75mm					
K.P.M. Drain (62)					
8203M ³ @ Rs 380.00/M ³					Rs 31243=00
④ Patch repair over pothole					
Drain (62) 8203M ²					
@ Rs 308.86/M ²					Rs 25336=00
⑤ Patch repair over bitum					
surface					
Drain (62) 8203M ²					
@ Rs 328.30/M ²					Rs 26972=00
⑥ Maintenance of road sign					
Drain (63) 0.170km					
@ Rs 1087.62/km					Rs 179=00
⑦ Maintenance of 200M 8km					
slope, Drain (63) 0.260km					
@ Rs 654.38/km					Rs 173=00
⑧ Maintenance of CD					
tube pipe contract, Drain (62)					
3 No @ Rs 1131.64 each					Rs 3395=00
⑨ Cutting of branches					
of trees, Drain (63) 2 No					
@ Rs 12.48 each					Rs 245=00

Continuation

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
(8) Cutting of shrubs.					
amrp-63	7	N	0		
Chaboo each					R ₀ 46=0000
(9) Trimming of grass.					
amrp-63	18	M	2		
@ Rs 2.20 / m ²					R ₀ 40=00
(10) Road marking.					
amrp-63	220	M	2		
@ Rs 942.89 / m ²					R ₀ 207436=00
(11) White washing.					
amrp-63	63	M	2		
@ Rs 16.48 / m ²					R ₀ 1038=00
					R ₀ 351848=00
Loss on 1% burn					R ₀ 1399=00
					R ₀ 350054=00
JE	27/3/25	AE	03/08/25	CEP	09/06/25
					EE

Continuation