

कार्यपालक अभियंता, का कार्यालय
ग्रामीण कार्य विभाग, कार्य प्रमंडल, सीतामढ़ी

पत्रांक 1322817 / दिनांक 17/06/25

प्रेषक,

कार्यपालक अभियंता,
ग्रामीण कार्य विभाग,
कार्य प्रमंडल, सीतामढ़ी।

सेवा में,

अपर मुख्य कार्यपालक पदाधिकारी—सह—सचिव,
ग्रामीण कार्य विभाग,
बिहार, पटना।

विषय:—


शीर्ष बिहार नई अनुरक्षण नीति 2018 (MR 3054) में आवंटन उपलब्ध कराने के संबंध में।

महाशय,

उपर्युक्त विषयक इस प्रमंडल अंतर्गत चल रहे नई अनुरक्षण नीति 2018 (MR 3054) में स्वीकृत योजनाओं के विभिन्न कार्यों के लिए संलग्न विवरणी अनुसार भुगतान हेतु आवंटन उपलब्ध कराने की कृपा की जाय।

अनु०:— यथोक्त।

विश्वासभाजन


17/6/25

कार्यपालक अभियंता,

ग्रामीण कार्य विभाग,

कार्य प्रमंडल, सीतामढ़ी।

Requisition Format for Scheme Head-MR (3054) under Bihar Rural Road Maintenance Policy-2018 (Initial Rectification and Surface Renewal)

Name of Works Division RWD, Works Division- Sitamarhi

Name of Works Division RWD, Works Division- Sitamarhi																			
Sl. No.	Package No.	Name of Road	Project ID as per MIS	Administrative Approval (AA) Letter No. & Date	Length (in Km)	Administrative Approval (AA)			Agreement Amount (in Lakh)		Agreement No. Date	Date of Completion as per Agreement	Value of IRI (in mm/km)	Thickness of Bitumen Layer (in mm)	Value of Bitumen Content in Percentage	Previous Total Allocated Amount (in Lakh)	Up-to Date expenditure as per MIS (in Lakh)	Requisition against work done (in Lakh)	Remarks
						Amount (in Lakh)	5 Years Routine Maintenance (in Lakh)	Initial Rectification With Surface Renewal (in Lakh)	5 Years Routine Maintenance (in Lakh)										
1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	
1	MR-N/23-24 Sitamarhi/17	L065,Surhar PMGSY Road to Saurinva (VR65)	31607902288	Lt. No.-1086 Dt.-01.03.24	1.750	126.772	13.898	121.67136	13.95354	08/ MBD/24-25	25.04.2025	3687	25mm	5.00%	66.62393	66.62393	11.99231		
					1.750	126.772	13.898	121.67136	13.95354						66.62393	66.62393	11.99231		

1. Signed Hard Copy and Soft Copy (in excel) of recorded IRI is enclosed
2. Up-to date Physical Progress has been uploaded in MIS

[Signature]
13/6/24
Executive Engineer
RWD (WP-Division)
Sitamarhi
13/6/24

FORM GFR 19-A

(See Government of India's Decision (1) below Rule 150)

Form of Utilization Certification up to the month of June 2025

Sl. No.	Name of Scheme	Sanction No. & Date with Amount (in lacs Rs.)	Amount Received (in Rs.)	Particulars
1	Construction of Rural Road New Maintenance Policy 2018	Up to Date Received Allotment	Rs. 2121482248.00	Certified that out of Rs 2121482248.00 received during upto date in favor of Executive Engineer Sitamarhi. Bihar a sum of Rs. 2019352380.00 has been utilized for the purpose of New Maintenance Policy 2018 Scheme as given in the margin for which it was sanctioned and that the balance of Rs 102129868.00 remaining unutilized at the end of the period under report
	Total:			

2. Certified that I have satisfied myself that the condition on which the grant-in-aid was sanctioned have been duly fulfilled /are being fulfilled and that I have exercised the following checks to see that the money was actually utilized for the purpose for which it was sanctioned.

Kind of Checks exercised:-

- I Works have been supervised by Executive Engineer/Superintending Engineer.
- li Periodical inspection has been conducted by Executive Engineer/Superintending
- lii Construction materials have been tested.
- lv Measurements have been recorded in the MBs and test check conducted by the Assistant Engineer/Executive Engineer
- V All other codal formalities

3. Physical Progress achieved:-

- I Construction of Road Works.
- li Construction of CD works

Executive Engineer,
R.W.D. Works

Division, Sitamarhi

Name of Road :- L065 Sutihar pmgsy road to Sautiniya

Date	Time	Section No.	Length in km	Bumps in mm	Speed Rate	OR mm/km	IRI CATEGORY mm/km ROAD	Latitude	ongitude	Event
28/3/25	11:39:11	67	0.1	280	0	2800	3313 G	26.51393	85.39434	Curve
28/3/25	11:40:21	67	0.1	340	0	3400	3994 G	26.51556	85.3938	Curve
28/3/25	11:41:0	67	0.1	280	10.1	2800	3313 G	26.51587	85.39291	Normal
28/3/25	11:41:32	67	0.1	280	10.1	2800	3313 G	26.51595	85.39195	Curve
28/3/25	11:42:0	67	0.1	320	10.1	3200	3767 G	26.5167	85.39158	Culvert
28/3/25	11:42:7	67	0.1	300	20.2	3000	3540 G	26.51756	85.39116	Normal
28/3/25	11:43:0	67	0.1	330	20.2	3300	3881 G	26.51837	85.39079	Normal
28/3/25	11:43:18	67	0.1	320	0	3200	3767 G	26.50881	85.40461	Normal
28/3/25	11:43:18	67	0.1	320	0	3200	3767 G	26.50881	85.40461	Normal
28/3/25	11:43:18	67	0.1	320	0	3200	3767 G	26.50881	85.40461	Normal
28/3/25	11:43:18	67	0.1	320	0	3200	3767 G	26.50881	85.40461	Normal
28/3/25	11:43:18	67	0.1	320	0	3200	3767 G	26.50881	85.40461	Normal
28/3/25	11:43:18	67	0.1	320	0	3200	3767 G	26.50881	85.40461	Normal
28/3/25	11:43:18	67	0.1	320	0	3200	3767 G	26.50881	85.40461	Normal
28/3/25	11:43:18	67	0.1	310	10.1	3100	3654 G	26.50813	85.40524	Speed Breaker
28/3/25	11:43:53	67	0.1	310	10.1	3100	3654 G	26.50813	85.40524	Speed Breaker
28/3/25	11:43:53	67	0.1	310	10.1	3100	3654 G	26.50813	85.40524	Speed Breaker
28/3/25	11:43:53	67	0.1	340	10.1	3400	3994 G	26.50813	85.40524	Culvert

62679

3687

Total IRI Sum


Total IRI Average

16/02/25

22/02/2019

Shivam . T.S.
28/08/25

File : C:\Users\Administrator\Desktop\Bump Reports\Sashi Ranjan Sing\02831517.Xls, Section No. : 57, Egn : Y =
 Name of Customer : Shashi Ranjan kumar, Name of Work/ Road : L065 Suthar Pmggy road to Sautiniya, Lab Job



Shashi
16/04/25

Shashi
28/03/25

Shivam
28/03/25
15