

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
	2nd	Year Maintenance			
N/W -	Basant Bazar Se				
	Pradkan maulai Road				
	to Choluta Sahi ke Pethas				
	Tak.				
N/C -	Dhirendra Kumar				
Agg no -	MMG SX/	SB2/01/	2022-23		
Date of work order					2/5/2022
Date of Completion					01/05/2023
<u>Measurement</u>					
Restoration of rain cuts					
with soil, maximum gravel etc					
	1x	2.85	1.71	0.30	1.46 m ³
	1x	5.96	1.28	0.30	3.36 m ³
	3x	2.91	1.89	0.30	4.94 m ³
	1x	4.28	1.96	0.30	2.51 m ³
	2x	2x 1.80	x 0.30		1.8324
	2x	3x 1.6	x 0.3		2.88
					15.15 m ³

Continuation

Material Statement	
① Soil	15.15w
② Stone Chills	0.31m
③ Bitumen Emulsions	3.15kg
④ Bitumen	21.17kg

Continuation