

5th year maintenance Bill

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Nature of work:- Maintenance of Road					
From NHBI Dwarika Bigha To village					
Bamohala.					
Agency:- Ravishankar Siroha.					
App. No:- 61-SBD/2018-19					
Actual Date of Completion:- 08/11/2019					

MEASUREMENT

① Restoration of rain cuts

-----do-----do-----do					
42x0.90x1.10x0.30	12.4744 ³				
36x1.25x1.10x0.30	14.8504 ³				
28x1.90x1.05x0.30	16.7584 ³				
22x2.15x1.05x0.30	14.9004 ³				
18x2.85x1.05x0.30	16.1604 ³				
12x3.15x1.00x0.30	11.3404 ³				
8x4.75x1.00x0.30	11.4004 ³				
2x7.80x1.00x0.30	4.684 ³				
1x9.10x1.00x0.30	2.734 ³				
	105.2924 ³				

② Maintenance of earthen shoulder

-----do-----do-----do					
2x8x11.40x1.00	182.404 ²				
2x6x14.60x1.00	175.204 ²				
2x4x18.30x1.00	146.404 ²				
2x2x20.25x1.00	81.004 ²				
	585.004 ²				

Continuation



Continuation