

MARRTO YADAVTOLA (UTARWARITOLA) I
AMHARI

Schedule XLV-Form No. 134

संसद कमेड डींग्ल
ममस्य (SC)

SITAMARI

DIVISION

FINAL

RIGA.

SUB-DIVISION

ममस्य-SC

3037

MEASUREMENT BOOK

27/3/11

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Content of area
	No.	L.	B.	D.	
	3rd	Year	Maintenance	Bill	
1) W.L. - Mason	To	From	To	0	Cut or War
Ag. No. -	60	S.B.D.	1020	21	
Agency -	Sai Sam	Yam	Kr. Singh.		
Maintenance	Period -	07	03.24	to 06.03.25	
	Measurement				

1) Restoration of Rain Cut.

16 x 4.70 x 0.90 x 0.30 =	20.30 m ³
18 x 5.40 x 0.80 x 0.30 =	23.33 "
18 x 3.90 x 0.70 x 0.30 =	14.74 "
22 x 6.40 x 0.90 x 0.30 =	38.02 "
18 x 3.05 x 0.90 x 0.30 =	14.82 m ³
	= 111.21 m ³

2) Maintenance of gutter channel.

16 x 4.70 x 0.80 =	60.16 m ²
18 x 5.40 x 0.90 =	87.48 "
22 x 6.30 x 1.0 =	138.60 "
22 x 3.90 x 0.70 =	60.06 "
26 x 7.30 x 1.0 =	205.40 "
18 x 4.10 x 0.90 =	68.42 "
	= 618.12 m ²

3) Maintenance of M.S. S. pool.

8 x 3.40 x 2.20 =	59.84 m ²
6 x 1.40 x 1.10 =	9.24 "
8 x 2.20 x 1.60 =	28.16 "
6 x 2.20 x 1.0 =	13.20 "
	= 110.44 m ²

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
			B.P. = 256		3093.0
	Add	17.2.0		2R	5631.0
	Add	127.654		2R	7571.0
	Add	107.5.0		2R	697.0
				2R	636.992.0

Kumar Shankar Ch
8.3.25 18/04/25
7.0 AE
26/6/25

Material Statement:-

1) Earth:-	176.13	M3 @ 23.78	M3 @	4188.0
2) S. chip:-	5.92	M3 @ 470.04	M3 @	2783.0
			2R	6971.0

Kumar
8.3.25
7.0