

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
DN/10 - Chitaga village to Deoga Chowak TAK					
② Agency - M/S JAL Construction Numa Bagra Maksudpur Hubanpur.					
③ Ags-120 - MMS 54/103D-53-2021-22					
① Restoration of Raincuts					
		19.7	0.80	0.90	= 14.18
		32.3	0.95	0.95	= 29.15
		23.0	1.2	0.75	= 20.7
		34.4	0.95	0.90	= 29.41
		14.95	0.85	0.75	= 9.53
		28	1.2	0.81	= 27.21
					130.18 m ²
② Maintenance of earthen Shallow					
		2	13	30	0.75 = 585 m
		2	4	5	0.70 = 140
					725 m ²
③ Repair to pot holes					
		1	4.65	2.3	= 10.70
		2	9.85	3.1	= 61.07
Shari		3	3.65	2.6	= 59.68
					100.24 m ²
④ Maintenance of already planted tree					
		108.60			Mos
⑤ Maintenance of home pipercut					
		1			Mos

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
① Restoration of Rain cuts.					
TMBP (57) 130 = 18 m ³					
Rs @ 404 = 06					= 52600 = 6
② Maintenance of earthen shoulders					
TMBP (57) 225 m ²					
Rs @ 60 = 28					= 43703 = 20
③ Repair to pot holes					
TMBP (57) 100 = 24 m ²					
Rs @ 267 = 16					= 26780 = 6
④ Maintenance of already planted tree 108 = 10 No					
TMBP (57) Rs @ 690 = 40					= 74563 = 20
⑤ Maintenance of lamp post					
TMBP (57) 1 No					
Rs @ 1166 = 58					= 1167 = 20
⑥ Maintenance of glass type Culvert of Chantry					
TMBP (58) 3 Nos					
Rs @ 2394 = 96					= 7185 = 6
⑦ Maintenance of Road sign way clearing					
TMBP (58) 2.75 km					
Rs @ 1104 = 15					= 3036 = 6
⑧ Maintenance of 200 M + KM stone					
TMBP (58) 2.75 TC					
Rs @ 748 = 22					= 2058 = 20
					R = 211092 = 20

Shan
23/01/2024
Continuation