

3rd year Maintenance

68

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Name of work- Maintenance of road from Champaran Tathandhi to Bairiya in kesaria Block					
Agency- HJS Balaji Construction					
Agreement No- 59 SBD/2018-19					
Date of start - 22/10/2019 ✓					
Date of Completion - 21/10/2020					
Actual date of Completion - 20/10/2020 ✓					
3rd Year Maintenance? 21/10/2022 to Period 20/10/2023 ✓					

~~① Maintenance of earth
shoulder~~

1	X	8.50	$\times 1.20 =$	10.20	11
2	X	7.40	$\times 1.25 =$	9.25	11
Q2	X	10.00	$\times 1.20 =$	12.00	11
Q1	V	6.10	$\times 0.90 =$	5.49	11
Q2	X	9.00	$\times 1.25 =$	11.25	11
1	X	8.10	$\times 1.20 =$	9.72	11
Q2	X	7.50	$\times 1.28 =$	9.40	11
1	X	6.50	$\times 1.20 =$	7.80	11
1	X	9.00	$\times 1.25 =$	11.25	11
Q2	X	7.50	$\times 1.10 =$	8.25	11
2	X	8.10	$\times 1.15 =$	9.16	11
Q3	V	6.40	$\times 1.10 =$	7.04	11
2	V	7.50	$\times 0.85 =$	6.42	11
Q3	V	10.00	$\times 1.25 =$	12.50	11
2	V	7.50	$\times 0.90 =$	6.75	11
Continuation				221.111	
113.62					

Abstract of cast

72

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
① Restoration of Rain sheets					
		55.85			
	Q-VTHB/P69	② = 77.261			
	c l - 365.25/11 - R.	20399~			
		20299=0			
② Maintenance of earthen shoulder					
		13.62			
	Q-VTHB/P68	① = 221.111			
	P69	③ = 166.731			
		387.841			
		280.351			
	c l . 54.37/11 - R.	15243=0			
		21087=0			
③ Maintenance of bitumen surface road					
④ Repair to Pot hole					
		149.751			
	Q-VTHB/P70	④ = 149.751			
	c l . 286.92/11 R.	19274=0			
		19869=0			
(i) Maintenance of worn road					
		149.751			
	Q-VTHB/P70	⑤ = 149.751			
	c l . 384.81/11 R.	19144=0			
		26648=0			
(ii) Patch repair					
		149.751			
	Q-VTHB/P70	⑥ = 149.751			
	c l . 271.15/11 R.	13499=0			
		18.777=0			
④ Maintenance of H. P. culvert					
		1 Nos			
	Q-VTHB/P70	⑦ = 1 Nos			
	c l . 1131.64/each R.	1132=0			
⑤ White washing on bench					
		26.531			
	Q-VTHB/P70	⑧ = 26.531			
	c l . 16.3015 - R.	446=0			
		116178=0			
		84128=0			

Continuation

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
⑥ cutting of branches of trees					
Q-VTMB/70 ⑥ = 8 Nrs					
e/f 107.48/each R 860/-					
⑦ cutting of shrubs					
Q-VTMB/71 ⑦ = 13 Nrs					
e/f 6.60/each R - 112.20					
⑧ Trimming of grass					
Q-VTMB/71 ⑧ = 314.00/-					
e/f 7.29/17 R - 200					
⑨ Painting 2 coats cement paint					
Q-VTMB/71 ⑨ = 86.00/-					
e/f 104.74/- R - 902.20					
⑩ Brown and laying Road					
Hauling					
Q-VTMB/71 ⑩ = 202.20					
e/f. 867.77/17 R 24557.77					
⑪ Maintenance of road					
sign					
Q-VTMB/71 ⑪ = 2.884 Km					
e/f. 1087.63/Km R - 3132.00					
⑫ Maintenance of 20mm store					
Q-VTMB/71 ⑫ = 0.212 Km					
e/f. 749=0/Km R 159.00					
R 376.612=0					
R 273.112=0					
Continuation					
					272245=0

2722452

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
		B.F	R.	272 312 = 00	
1.083 0.05% below	136	272 137 = 00			
		R.	376 124 = 00		
		R.	272 975 = 00		
Shedding				272 109 = 00	
22-10-23					
2.6					
51.124					
Ae					
INVOICE NO - 2021232238100671					
Vidhi - 1m B.P. 60					
at 1.56 mT					
used in 84.42 m ² + 10.4 m ²					
+ 3.44 m ² + (-) 0.765 mT					
Balan 0.795 mT					

Materials statement

- (i) Soil - 589 m³
- (ii) Metal - 6.28 m³ 4.51 m³
- (iii) Chipp - 3.73 m³ 2.69 m³
- (iv) Screening - 0.85 m³
- (v) Sand - 0.63 m³

Shedding			
22-10-23			
2.6			
51.124			
Ae			
C/S			
soil			
21-2-25			
21-02-2025			
Ae.			
25			
soil			
TS			