

3rd year Maintenance Bill

43

Sch. XLV—Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Name of Road -					Maintenance of
Road from NH 30A to Dambura					
Road to Kharjannua Hahadalit Tola.					
Agency -					Jai mata Construction
Agreement No -					28/SBP/2018-19
Date of Commencement -					20/07/18
Actual Date of Completion -					16/04/19
Date of Entry -					

RECORD ENTRY

Restoration of Rain cuts

22x	1.10x	1.20x	0.30	8.712m ³
20x	1.25x	1.20x	0.30	9.000m ³
16x	1.35x	1.20x	0.30	10.08m ³
12x	2.25x	1.20x	0.30	9.72m ³
8x	3.90x	1.20x	0.30	11.232m ³
6x	4.50x	1.20x	0.30	9.72m ³
4x	5.90x	1.20x	0.30	8.496m ³
6x	5.00x	1.10x	0.30	9.90m ³
				76.86m ³

(2) Maintenance of Earthen Shoulder

28x	1.50x	1.20	50.40m ²
22x	1.90x	1.20	50.18m ²
18x	2.35x	1.20	50.78m ²
12x	3.70x	1.20	53.28m ²
10x	4.30x	1.20	51.60m ²

Continuation

256.24m²

Continuation