

5th year maintenance Bill

52

Sch. XLV—Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Name of work- Maintenance of Road					
NH 309 Gadapura Road To Kharjuna Naka					
Agency- Jalnaa Construction					
Aggr. No- 28/830/2018-19					
Actual date of completion- 16/04/2019					
<u>MEASUREMENT</u>					
1) Restoration of rain cuts					
.....					
	26	0.60	1.20	0.30	5.61643
	24	0.80	1.20	0.30	6.91243
	22	0.90	1.20	0.30	7.12843
	18	1.25	1.15	0.30	7.36343
	14	1.65	1.10	0.30	7.62843
	12	1.95	1.10	0.30	7.72243
	8	2.25	1.10	0.30	5.94043
	6	2.60	1.15	0.30	5.38243
	8	3.15	1.15	0.30	8.69443
	6	3.45	1.10	0.30	6.83143
	16	1.25	1.20	0.30	7.20043
	12	1.40	1.10	0.30	5.54443
	14	1.90	1.00	0.30	7.98043
	8	2.05	1.00	0.30	4.92043
					95.2543
2) Maintenance of Embankment shoulder					
.....					
	2	1.2	3.60	1.20	103.6843
	2	8	4.90	1.20	94.0843
	2	6	7.40	1.10	93.6843
					295.4443

Continuation

295.4443

Continuation