

3rd year maintenance

32

Sch. XLV—Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Must Logo Madanpur Karmaharaj shakur					
ke ghasee Sandharaj shakur 1c					
ghay tal.					

Agency - Sd. Krishan Kumar

Ag. No - 21 (SAD) / 2020-21

D.O.W - 10.08.2020

Actual D.O.C - 29.01.2022

Details -

① Restoration of Raincut

12x 2.15x 0.90x 0.30 = 6.97

16x 2.40x 0.80x 0.30 = 9.22

14x 2.10x 0.85x 0.30 = 7.50

11x 2.30x 0.95x 0.30 = 7.21

10x 2.45x 0.75x 0.30 = 5.51

15x 2.60x 0.90x 0.35 = 11.81

09x 2.10x 0.80x 0.30 = 4.54

52.76 m³

② Making up of Berms

10x 7.00x 0.85 = 59.50

14x 8.00x 0.75 = 84.00

17x 5.00x 0.80 = 68.00

10x 4.00x 0.60 = 24.00

235.50 m²

③ Repair of hot holes filled

with 75 mm wdg

4x 2.90x 1.45 = 15.66

6x 2.40x 1.30 = 18.72

Continuation

34.38

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
					B.F. - R 203049 =
Accl list + L. (134)					Et) R 26396 =
Accl S. Fee					Et) R 746 =
					R 230,191 =
Less 0.45 % Below					Et) R 1147 =
					R 229,040 =

Pl
31/01/2025
JK

Material Statement

C/w - 88.086 m³

S/mul - 4.39 m³

S/chips - 2.61 m³

R-2 - 19.27 kg

Bitumen - 0.206 MT

Pl
31/01/2025
JK