

5th year maintenance

17

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
None of work - main of road					
from Baghpur colony road se					
Ran chresth. Rai ke bhar dais					
Agency - vijay Kumar Ravshan					
Agreement No -				69/2018-19	
Date of start -				19.01.2019	
Date of completion -				18.01.2020	
Record End					
1 Restoration of drain					
ends with soil					
- do -					

6	x	4.60	x	1.05	x	0.30	=	8.69
9	x	5.40	x	0.70	x	0.30	=	13.12
2	x	6.30	x	0.80	x	0.30	=	10.58
9	x	4.80	x	0.85	x	0.30	=	11.02
12	x	4.40	x	0.70	x	0.30	=	11.09
9	x	5.80	x	0.95	x	0.30	=	14.88
6	x	4.75	x	1.00	x	0.30	=	8.55
9	x	8.60	x	0.80	x	0.30	=	14.26
8	x	3.30	x	0.70	x	0.30	=	5.54
Total								97.73

2	main of earthen							
Sewers - do -								
2	x	9	x	6.60	x	0.80	=	95.04
2	x	12	x	5.30	x	1.10	=	153.12
2	x	16	x	4.90	x	0.90	=	141.12

Continuation

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
4. patch repair on port holes - do -					
26.52 m ² wide page (10)					
el 222.98/m ²				4	21454
5. paint of main pipe columns - do -					
0.1 m ² wide page (13)					
el 113.64/m ²				4	1132
8. paint of roof signs - do -					
110.74 m ² wide page (13)					
el 1082.63/m ²				4	1168
2. paint of wall main stone					
0.258 m ² wide page (18)					
el 738.55/m ²				4	191
8. cutting of branches of steel - do -					
0.6 m ² wide page (13)					
el 107.43/m ²				4	645
9. priming of cross members - do -					
290.2 m ² wide page (19)					
el 2.20/m ²				4	638
				4	123827
cell 102.6 m ²				4	12383
				4	11444

Sham
07/02/2018
Continuation