

Sch. XLV-Form No. 134					
Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
<u>5th year Maintenance</u>					
① N/w - Soupar vipin Rai					
Shop to Banghosi Mahadalit					
Nala Nak kosi byssy					
N/C - Amit ko Anal					
Agg no - MMLSY/SBD/S9/18-19					
Date of work start = 16/01/19					
Date of work completion 15/01/20					
① Restoration of rain					
cuts with Soil Mortar					
gravel etc					
	2	2.25	2.1	0.30	2.83
	4	5.21	1.95	0.30	12.19
	5	6.75	1.25	0.30	12.65
	3	4.75	1.78	0.30	7.60
	7	1.85	1.5	0.30	5.827
	6	6.25	1.45	0.30	16.31
	5	4.5	1.9	0.30	12.82
	2	8.5	1.45	0.30	7.39
	3	5.5	1.75	0.30	8.66
	2	4.85	1.65	0.30	9.80
					91.07m ³
② Maintenance of Earth					
Shoulder					
	2 x 25 x	1			50m ²

~~Shaw~~
~~25/01/25~~ AE

- (i) Soil - 91.07 m^3
(ii) Bitumen - 508 MT
(iii) RS - 0.0735 MT
(iv) Stone (Rif) = 7.22 m^3