

MMGEYI - (SC)

Schedule XLV-Form No. 134

N. 1022 Road to Salim nagar Thapat tola.

Emergency: - Amit Kumar, Buxar.

R. CO. D COOR 8 **DIVISION**

Kishanagar-1

R. CO. D COOR 8 **SUB-DIVISION**

Teshagachh.

MB No - 3026

MEASUREMENT BOOK

Amit Kumar

2nd year Maintenance Bill.

70

Sch. XLV—Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
N/W's Load Road to					
Salim Nagar					
Thapat 256					
Agency:- Amit Kumar					
Valid start - 09/07/20					
Valid comp - 08/07/21					

Measurement

① Restoration of Ravine

$$6 \times 30.0 \times 1.15 \times 0.2 = 41.40$$

$$7 \times 30.0 \times 1.40 \times 0.1 = 23.10$$

64.5

m²

② Maintenance of Eastern Shoulder

$$4 \times 30.0 \times 1.15 \times 1.38 = 138.00$$

$$5 \times 30.0 \times 1.10 \times 1.10 = 110.00$$

$$5 \times 30.0 \times 1.10 \times 1.10 = 110.00$$

358.00

m²

③ Repair of pot holes

$$1 \times 10.0 \times 0.1 \times 1.00 = 1.00$$

$$2 \times 30.0 \times 0.2 \times 2.00 = 12.00$$

$$4 \times 30.0 \times 0.3 \times 3.00 = 36.00$$

$$1 \times 20.0 \times 0.1 \times 2.00 = 2.00$$

51.00

Limit: 50.00

m²

Continuation

Continuation