

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
3rd year maintenance					
Repair & maintenance					
of Road from	503240				lengthwise
to					
Aug. Grammar school					
Amount	69800			2000-21	
Debit				24/3/2012	
Debit				21/3/2012	
① Restoration of Rain					
cuts with all components					
10 x 15m x .90 x .30 =					40.50
10 x 15m x 2.75 x .30 =					67.50
4 x 15m x 6.0 x .30 =					10.80
					118.80m ³
2. Making up of Berms.					
Shoulder with all components					
10 x 2 x 15m x .90 =					270m ³
10 x 2 x 15m x .75 =					225
6 x 2 x 15m x .60 =					108
3 x 15m x .45 =					20.25
					623.25m ³
					623.03m ³
3. Repair of Potholes					
filled with 75 mm stone					
4 x 3m x 9m x .075 =					1.80m ³
6 x 4m x 1.50 x .075 =					2.70
7 x 2.50m x 1.80 x .075 =					2.362
13 x 2m x 1.20 x .075 =					0.54

[illegible]