

1ST ON A/c BILL

1

Name of work -

Situation of work -

Agency by which work is executed -

Date of measurement -

No. and date of agreement

(These four lines should be repeated at the commencement of the measurements relating to each work.)

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
<u>Name of work</u> -					
<u>Agency</u> -					
<u>Agreement No</u> -					
<u>Agreement value</u> (C) Rs					
<u>Date of start</u>					
<u>Date of Completion</u>					
<u>Date of measurement</u> -					
<u>RECORD MEASUREMENT:-</u>					
①					
②					
③					
④					
⑤					
⑥					
⑦					
⑧					
⑨					
⑩					
⑪					
⑫					
⑬					
⑭					
⑮					
⑯					
⑰					
⑱					
⑲					
⑳					
㉑					
㉒					
㉓					
㉔					
㉕					
㉖					
㉗					
㉘					
㉙					
㉚					
㉛					
㉜					
㉝					
㉞					
㉟					
㊱					
㊲					
㊳					
㊴					
㊵					
㊶					
㊷					
㊸					
㊹					
㊺					
㊻					
㊼					
㊽					
㊾					
㊿					

Continuation

5th year main Bill

60

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
N/w- pitch road to horizon Tola lower sita Bardaha under NMWS (sc) road. scheme.					
Agency - Shalendra Shukla Mishra					
Agreement No - 8/SBD/NMWS (sc) 2018-2019					
Actual Date of completion - 18/9/2019					
Date of Measurement -					
1. Restoration of Rainwater Berm with soil - as per.					
2x 5x 10.00 x 1.00 x 0.25m - 25.00m ²					
1x 8x 25.00 x 1.00 x 0.25m - 30.00m ²					
1x 4x 6.00 x 1.00 x 0.25m - 6.00m ²					
2x 2x 17.00 x 0.30m - 20.40m ²					
					81.40m ²
Limit Qty -					80.19m ²
2 Making up berm shoulder, stripping - as per.					
2x 8x 10.00 x 0.90m - 144.00m ²					
2x 6x 16.00 x 0.80 - 153.60m ²					
2x 4x 11.00 x 0.90 - 79.20m ²					
2x 2x 19.08 x 0.90 - 68.69m ²					
					445.50m ²

Continuation

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
ABSTRACT OF COST					
Date of entry -					
(1) Restoration of Rain cut & dry vide p No -					
(60) Item (1) 80.14 M ³					
@ 11959.74/M ³ - Rs					28848/
(2) Making up berm/shoulder					
dry vide p No - (60)					
Item (2) 448.50 M ³ @					
Rs 53.70/M ³ - Rs					23922/
(3) Repair of pot holes filled with vide p No -					
(61) Item (3) 6.06 M ³					
@ Rs 11383.45/M ³ - Rs					68984/
(4) Patch repair over pot holes with vide p No - (61) Item (4)					
103.13 M ² @ Rs 219.66/M ²					
- Rs					22652/0
(5) Patch repair over bituminous surface					
dry vide p No - (61)					
Item (5) 103.13 M ²					
@ Rs 308.26/M ² - Rs					31789/0
(6) Printing New letters					
dry vide p No - (62) Item					
(5) 100.00 prcm @					
Rs 0.82/prcm =					906/0

Continuation

Rs 177201/0

Sch. XLV-Form No. 134

B/F- 353506/00

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
19 15.13					
White Wading of					
Parapet on Y side					
PHO. (63) Item (13)					
25.56 m ² @ 16.47/m ²					
					421/00
					353927/00
Less 0.13 % as per					
agreement (2) is					480/00
					353467/00
25.56 20/11/15 R					
					DA0
					CSP
					(1) work
					25/2/25